



127739

RECORDED  
HILLSDALE CO. MICH.

LIBER 3 PAGE 198  
HILLSDALE COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

'97 OCT 30 AM 10 18

*Julie VanZandt*  
REC. OF DEEDS

For corners in

<u>Hillsdale</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>7S</u> R <u>3W</u>	<u>E-1</u>
	T <u>  </u> R <u>  </u>	<u>  </u>
	T <u>  </u> R <u>  </u>	<u>  </u>
	T <u>  </u> R <u>  </u>	<u>  </u>
2. Property Controlling in Section	S <u>  </u> T <u>  </u> R <u>  </u>	<u>  </u>
	S <u>  </u> T <u>  </u> R <u>  </u>	<u>  </u>
3. Miscellaneous	S <u>  </u> T <u>  </u> R <u>  </u>	<u>  </u>
Property in Sec.	S <u>  </u> T <u>  </u> R <u>  </u>	<u>  </u>

SURVEY &  
REMONUMENTATION

FEB 11 1998

Register of Deeds Stamp & File Number

4. Lot No.   , Recorded Plat     
5. Private Claims   

Frederick J. Cutcher, in a field survey on 9/23, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	10		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original Government Survey by William Brookfield, 1825: R. Oak 16" S. 61° E. 66 links;  
W. Ash 14" S. 21½° W. 43 links.

Survey No. 788, George Mark, 12/18/1877: Stone; stone S. 45° W. 70 3/4 links.

Survey No. 824, George Mark, 3/10/1879: Stone, S. 45° W. 70 3/4 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

On 9-23-97 I found nothing.

No witnesses were found. Measured G.L.O. distance of 54.12' East of E-13, Town 6 South, Range 3 West and set corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I set a County remonumentation bar and cap in a monument box G.L.O. distance of 54.12' East of E-13, T6S, R3W, and is accepted as best available evidence of the position of the original corner.

In centerline Bankers Road. In line with centerline of Lake Wilson Road to South  
Nail & spotter S. side power pole N. 73° E. 66.50'  
Fd. P.K. N. side power pole S. 62° E. 59.70'  
Top cen. tel. stan. S: 70° W. 61.30'  
Fd. P.K. N. side power pole N. 77° W. 132.15'

Signed by Frederick J. Cutcher  
Surveyor's Michigan License No. Frederick J. Cutcher 24592

Date 10/29/97

