127736 LIBER 3 PAGE 195

HILLSDALE COUNTY REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

| RECORDED |        |         |  |  |  |  |  |  |  |
|----------|--------|---------|--|--|--|--|--|--|--|
| -1.      | LSCALE | 11.8:03 |  |  |  |  |  |  |  |

\*97 OCT 30 AM 10 18

## SURVEY & REMONUMENTATION

FEB 1 1 1998

SECTION
Register of Deeds Stamp & File Number

| ે<br>વ   |   |               |
|--|---|---------------|
| Hillsdale<br>(County)  | Located In:                                       | Corner Code # |
| Property Controlling in Section Miscellaneous Property in Sec. | T_7S_R3<br>TR<br>TR<br>TR<br>S TR<br>S TR<br>S TR | 3W I-2        |

, Recorded Plat 4. Lot No. 5. Private Claims

Frederick J.

in a field survey on 9/16, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

| A   | В                    | C            | D                  | E | F                  | G   | Н        | E  | J                  | ĸ   | L                 | M |
|-----|----------------------|--------------|--------------------|---|--------------------|-----|----------|----|--------------------|-----|-------------------|---|
| 1   |                      | T            | T                  |   | T                  |     |          |    |                    |     |                   |   |
| 2   | -6-                  | $\dashv$     | - 5-               | + | - 4 -              | +   | — á      | ٠  | - <u>2</u> -       | - - | - 1.              |   |
| 3   |                      |              |                    |   |                    | +   | +        | _  |                    | -   | +                 |   |
| 4 - | - <u>7</u> -         |              | - 8-               | - | -  <br> -          | +   | -10-     | -  | -1 <b>1</b> -      |     | -1 <sup>1</sup> 2 |   |
| 5 – | +                    | +            | +                  | + | _                  |     | -        |    | -+-                |     |                   | _ |
| 6   | -1 <mark> </mark> 8- | -            | -1,7-              | + | -1 <sub>6</sub> -  | - - | -15      | -  | -14-               |     | -13               |   |
| 7 — |                      | - -          | - -                |   | - -                | +   | +        |    |                    | -   | +                 |   |
| 8   | -1,9-                | +            | -20-               |   | -21-               |     | -22-     | +  | -2 3-              |     | -24               |   |
| 9 _ | -                    | _ -          |                    |   |                    | -   | +        | -  |                    |     | +                 |   |
| 10  | _30-                 | $\downarrow$ | -2 <sup>1</sup> 9- | - | 28-                | _   | -27-     | 1  | −2 <sub>.</sub> 6- |     | 2 <sub>5</sub>    |   |
| 11  |                      |              | - -                |   | -                  | -   |          | -  | +                  |     | -                 |   |
|     | <br>-31-             | _ _          | ∫<br>32            |   | -3 <sup>1</sup> 3- | _   | <br>_34_ | 1  | 3 <sub>.</sub> 5   | _   | -3 <sub>5</sub>   |   |
| 13  |                      |              |                    |   |                    |     |          | ╝. |                    |     |                   |   |

A. Description of original monument and accessories and/or subsequent restoration:

Original Government Survey by William Brookfield, 1825: Beech 10" S.  $49\frac{1}{2}$ ° W. 24 links; Beech 13" N.  $36\frac{1}{2}$ ° W. 8 links.

Records of Ringenberg, no date (A.J. Hatt): Iron pipe; poplar N.W. 42.85'; 3" stump fence corner East 31.5'; power pole S.E. 68.6'.B.

This corner was recovered by J.E. Maxson in August 1995 and prior to paving of Hillsdale Road a monument box was set by contractor.

B; Description of corner evidence found and/or method applied in restoring or reestablishing corner:

On 9-16-97 I found a 3/4" iron rod in monument box in centerline Hillsdale Road.

No witnesses were found.

🔅 Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I set County remonumentation cap on 3/4" iron rod in the monument box and is accepted as best available evidence of the position of the original corner.

In centerline Hillsdale Road.

Found P.K. N. side power pole S. 78° E. 30.41'

Found 60D spike w/ribbon S. side R.R. tie anch. post N. 63° W. 36.00'

Found P.K. E. side power pole S. 13° E. 120.55'

Set nail & spotter in S. side 4th wood fence post N. 50° E. 42.59'

Luderick V. Cutcher Surveyor's Michigan License No.

Date <u>October</u> 10/29/97

FREDERICK CUTCHER SURVEYOR OFESSIONP