



036203 RECORDED HILLSDALE CO. MICH.

00 NOV 17 PM 3:41

LIBER 5 PAGE 56

HILLSDALE COUNTY REMONUMENTATION CORNER  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

July Van Zandt  
REG. OF DEEDS

For corners in

HILLSDALE COUNTY	Located In:	Corner Code #
READING TWP (County)		
1. Public Land Survey	T 7 S R 4 W	A-5
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	

SURVEY &  
MONUMENTATION

JAN 12 2001

SECTION

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, EDWARD W. REED, in a field survey on NOVEMBER 1, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

SOUTHWEST CORNER, SECTIONS 7 & NORTHWEST CORNER, SECTION 18,  
READING TOWNSHIP, HILLSDALE COUNTY, MICHIGAN

A. Description of original monument and accessories and/or subsequent restoration:

GLO CORNER SET  
GLO CLOSING ON CORNER @ 77.58 CHAINS WEST OF C-5 CORNER AND 105 LINKS NORTH OF M-5, TOWN 7  
SOUTH, RANGE 5 WEST  
1867: MARKS, SURVEYOR-STAKE & STONE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

CORNER NOW UNDER ROCK & RUBBLE PILE  
PILE PUSHED UP TO CLEAR ALL TRACES OF FENCELINE NORTH  
FENCELINE SOUTH ALSO PUSHED INTO ROCK & RUBBLE PILE  
RESET CORNER USING C-5, TOWN 7 SOUTH, RANGE 4 WEST, AND OLD FENCELINES FITTING SURVEY OF 1867  
ALSO FITTING CORNERS L-5 AND M-5 OF TOWN 7 SOUTH, RANGE 5 WEST  
SET 3/4" X 30" REBAR IRON WITH REMON CAP WITH CARSONITE MARKER ALONG SIDE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 3/4" X 30" REBAR IRON WITH REMON CAP WITH CARSONITE MARKER ALONG SIDE	
CORNER M-5 ALGANSEE	S69.3'
CENTERLINE	SOUTH 34.0'
ROUND CONCRETE ANCHOR POST	N86E 317.08'
CENTER OF 60" OAK	N84E 279.3'
POWER POLE	N1E 90.37'
CENTER OF TRIPLE BOX ELDER	S1E 110.64'

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL REESTABLISHMENT  
OF THE POSITION OF THE ORIGINAL CORNER.

Signed by Edward R. Reed

EDWARD R. REED

Surveyor's Michigan License No. 33985

Date NOVEMBER 1, 2000

