034007

CO SEP 14 AM 11:35



## LIBER 5 PAGE 4 HILLSDALE COUNTY REMONUMENTATION CORNER LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Suery Canjanar 813.0FDEEDS

For corners in		
HILLSDALE COUNTY Located In: Corner C	ode #	SURVEY & EMONUMENTATION
1. Public Land Survey	\ \	JAN 1 2 2001
7 R	\	SECTION
3. Miscellaneous       S T R		Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat		ABCDEFGHIJKL
5. Private Claims		2 5 4 3 - 2 1
		3
		4 - 7 - 8 - 9 - 10 - 11 - 12
I, <u>EDWARD W. REED</u> , in a field survey on <u>AUGUST 16</u> , 2 hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the comentioned in lines 1 and 2 above were in conformance with regulations and rules the required in the current manual of survey instructions of the United States Department of the survey instructions.	the corner points rules therefore as lent of the interior,	5 -18 -17 -16 -15 -14 -13
of Land Management or by a decree of a Court of law and for that	the corner points	8 9 20 21 22 23 24
mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Land Surveyors or by a Decree of a Court of Law; established, re-establish	led, monumented,	9
recovered, found as expressed below:		10 30 29 28 27 26 25
NOTE: Not more than 2 corners, all in the same town and range, may be record	led	11
on this certificate.		12 31 32 33 34 35 36
		13
QUARTER CORNER COMMON TO SECTIONS 10 AND 15 READING TOWNSHIP, HILLSDALE COUNTY, MICHIGAN.		
A. Description of original monument and accessories and/or subsequent	restoration:	
1825: GLO CORNER SET 1881: GLO MARK - STONE AND BRICK		
1997: RINGENBERG: FD LARGE NAIL IN LINE WITH FENCE LINE RU AND WITNESSED	JNNING SOUTH,	SET ½" REBAR
B. Description of corner evidence found and/or method applied in restor	ring or reestablishir	ng corner:
FD $\frac{1}{2}$ " x 18" REBAR AND FLAGGING IN LINE WITH NEW FENCE ( SET 3/4" x 30" IRON WITH REMON CAP SET CAST IRON BOX 4" BELOW GRADE OF ROAD	10 YEARS +/- )	
C. Description of monument for corner and accessories established to	o perpetuate locati	
3/4" IRON WITH REMON CAP IN CAST IRON MONUMENTATION	BOX	EDWARD
NAIL IN EAST SIDE OF ROAD CORNER POST	SOUTH 29.46	6' W. REED
NAIL IN EAST SIDE OF 14" WALNUT	N3°W 32.9	V. THE THEFT I P.
TOP CENTER OF FIFTH WOOD POST, WEST OF ANCHOR POST TAG IN SOUTHWEST SIDE OF 8" HICKORY	S67°W 60.50 N67°W 81.9	25 8 OCHV. CH 2 45

AND IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL GORNER.

Signed by \_\_\_\_\_\_\_ Date \_\_\_AUGUST 16, 2000 \_\_\_\_\_

Surveyor's Michigan License No. 33985

33985 ED LAND SU