

ACCEPTED BY THE HILLSDALE  
SURVEY PEER GROUP AS THE  
CORNER UNDER MICHIGAN PUBLIC ACT  
OF 1900 A MEETING HELD ON  
Oct 11 2000  
John E. Bieszk  
ALBINGENBERG, CO. REC.

034940

RECORDED  
HILLSDALE CO. MICH.

00 OCT 11 AM 10:31

LIBER 5 PAGE 22  
REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

HILLSDALE

(County)

Located In:

Corner Code #

1. Public Land Survey

T 8S R 1W E-11

2. Property Controlling  
in Section

S T R

3. Miscellaneous  
Property in Sec.

S T R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, Jeffrey A. Bieszk, in a field survey on 6 Oct., 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

SURVEY &  
REMONUMENTATION

JAN 12 2001

SECTION

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO set by Ziba Swan (1824) Geo Mark (1869) survey #512  
10" Beech N68W 20 lks and (1876) survey #734  
6" Maple N23E 26 lks Stone, Stake and Brick

Robert Burris LCRC L1-P401  
Found iron pipe 2.5' west & 1.5' South  
intersection Roads  
PK nail Power Pole S40E 67.29 ft.  
PK nail 16" Maple S20W 65.33 ft.  
PK nail 24" Maple S50W 42.96 ft.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron as witnessed by Burris, dug under iron and found small portions of brick but no stone. Accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" iron w/cap in Monument Box  
PK nail Power Pole S 40 E 67.29 ft  
Nail w/tag 18" Hickory S 35 E 55.56 ft.  
Nail w/tag Power Pole N 50 W 57.36 ft.  
Stop Sign N 15 W 43.24 ft.



Signed by [Signature]  
Surveyor's Michigan License No. 41093

Date October 11, 2000