

ACCEPTED BY THE HILLSDALE COUNTY
SURVEY PEER GROUP AS THE OFFICIAL
CORNER UNDER MICHIGAN PUBLIC ACT 268
OF 1969-85. A MEETING HELD
ON 10-19-00 AT 8:00 PM
AL RINGENBERG

LIBER 5 PAGE 25 034943

RECORDED
HILLSDALE CO. MICH

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

00 OCT 11 AM 10:31

For corners in

HILLSDALE

(County)

Located In:

Corner Code #

1. Public Land Survey

T8S R 1W H-11

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

SURVEY &
REMONUMENTATION

JAN 12 2001

SECTION

Register of Deeds Stamp & File Number

I, Jeffrey A. Bieszk, in a field survey on 6 Oct. 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		13		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO set by Ziba Swan (1824) Geo. Mark (1876) survey #735
34" Beech S41E 21 lks Stake, Stone, brick & Earthen
6" Ironwood N56W 13 lks 5" Elm S73E 150 lks

Glenn E. Richards LCRC L1-P611
Found 1" Galv. Pipe
NE tele. Pedastal S10W 13.3 ft.
Nail & disk 6" Apple N70E 76.35 ft.
Nail & disk 30" Maple S40E 24.94 ft.
Nail & disk 36" Maple N70W 107.1 ft.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Glenn Richard found galv. pipe which checked with witnesses he got from Alan Ringenberg dated 6/21/78. I found galv. pipe as witnessed by Richards, dug under and found no stone. Pipe 3 feet North of South edge of Road. Accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" iron w/cap in Monument Box
Nail w/tag 48" Maple S 40 E 24.69 ft.
Nail w/tag 6" double Apple N 30 W 27.34 ft.
Nail w/tag 48" Maple N 70 W 106.49 ft.
Phone Riser S 02 W 15.27 ft.



Signed by [Signature]
Surveyor's Michigan License No. 41093

Date OCTOBER 11, 2000