



LIBER 5 PAGE 32

REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

034950

RECORDED  
HILLSDALE CO. MICH.

00 OCT 11 AM 10:31

Jeffrey A. Bieszk  
REG. OF DEEDS

For corners in

HILLSDALE

(County)

Located In:

Corner Code #

## 1. Public Land Survey

T 8S R 2W C-5

T R

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

## 3. Miscellaneous

S T R

Property in Sec.

S T R

SURVEY &  
REMONUMENTATION

JAN 12 2001

SECTION

Register of Deeds Stamp &amp; File Number

4. Lot No. , Recorded Plat

5. Private Claims

Jeffrey A. Bieszk

6 Oct. 2000

I, Jeffrey A. Bieszk, in a field survey on 6 Oct. 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

## A. Description of original monument and accessories and/or subsequent restoration:

GLO set by Wm. Brookfield. (1825)

Geo. Mark (1868) survey #474

14" R. Oak S56E 20 lks

20" R. Oak S57 1/4 W 21.5 lks

24" W. Oak S05W 34 lks

Geo. Mark (1905) survey #1241

20" Stone, glass &amp; Earthen

18" Double W. Oak S45 1/2 E 76.5 lks

5" Hickory N33W 20.5 lks

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/4" x 24" smooth iron 2.5 feet East of centerline of Road. Dug under iron and found nothing. Accepted as the best available evidence of the position of the original corner.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:


Set 5/8" x 36" iron w/cap in Monument Box

6" Oak N 15 E 51.46 ft.

48" Oak S 40 E 40.18 ft.

8" Poplar S 15 W 74.57 ft.

12" Oak N 80 W 38.83 ft.

Signed by Jeffrey A. BieszkSurveyor's Michigan License No. 41093Date Oct 11, 2000