SUNVEY & REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

DEC 1 6 1996

Surveyor's Michigan License No.

25863

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER J PAGE 291

For corners in 10NIA COMMUNICATION Corner Code #			,					
10NIA Located In: Corner Code #	STATE OF MICHIGAN IONIA COUNTY RECEIVED FOR RECORD							
1. Public Land Survey				6 2:1:		,		
T R			DIANE	K. AD	AMS .			
2. Property Controlling STR	egiste	REGISTER OF DEEDS gister of Deeds Stamp & File Number						
4. Lot No, Recorded Plat	,	. в	C D	E F (Э Н I	IJK	L M	
5. Private Claims	2	6	5	4	3	2	1	
i, MARINUS MULDER , in a field survey on OCTOBER 23, 19 9 6 ,	3 4	7	8	9	10	11	12	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Lar	ie 🧻	18	17	16	15	14	13	
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3 4 and above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of Court of Law, established, re-established, monumented, re-monumented, recovered, found a	5 7 a s 8	19	20	21	22	23	24	
expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded	9 10	30	29	28	27	26	25	
on this certificate.	11 12	31	32	33	34	35	36	
A. Description of original monument and accessories and/or subsequent restoration: THIS CORNER WAS FIRST ESTABLISHED BY U.S. DEPUTY SURVEYOR, JOHN MULLETT IN 1831. A WOOD POS WAS SET WITNESSED BY A 9" HICKORY N 44° W 16 LINKS AND A 8" BEECH N 48° E 28 LINKS. PERPETUATION: FORMER IONIA COUNTY SURVEYOR, THOMAS CORNELL PERFORMED A SURVEY OF SECTION PAGE 88 OF THE IONIA COUNTY SURVEYORS RECORDS. CORNELL CALLED FOR STAKE & STONES BUT GAVE THE IONIA COUNTY ROAD COMMISSION IMPROVED AND PAVED PECK LAKE ROAD. THE WITNESS INDEX SHIPPINTED STONE WITNESSES BY: 12", ELM N.E. 47.00 FEET 22", CHERRY N.E. 63.40 FEET M.B.T. POLE S.E. 53.41 FEET 20" CHERRY S.W. 48.16 FEET	N 15, DI NO WIT	NESSE	S FOR I	7.				
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: AT, THE ROAD SURFACE FOUND A NAIL & WASHER. AT A DEPTH OF 8" FOUND A 1" X 15" IRON ROD. AT A ACCEPTED THIS AS A PERPETUATION OF THE ORIGINAL CORNER. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:								
SET A 14" LONG ALUMINUM MONUMENT WITH A 4" DIAMETER CAP STAMPED "IONIA COUNTY- 25863" IN WITNESSED BY: NAIL & TAG SOUTH SIDE 18" APPLE N 67° E 56.98 FEET NAIL & TAG WEST SIDE 14" ELM S 22° W 65.18 FEET NAIL & TAG WEST SIDE POWER POLE N 12° W 89.08 FEET CENTERLINE OF ROAD SIGN POST S 43° E 42.41 FEET	Rati	fled	by P	607 G	quoti	F THE S	HUNE	
MARINUS A MULDER LAND EURVEYOR No. 25863	Date	/1	-/3-	5 Cou - <i>9</i> C er, Cha	2			

11-20-96