

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. PA 1970

For Corners In: \_\_\_\_\_ Located In \_\_\_\_\_ Corner Code # \_\_\_\_\_  
IOSCO \_\_\_\_\_  
(County)

1. Public Land Survey T 24N R 8E L-3  
T \_\_\_\_\_ R \_\_\_\_\_  
2. Property Controlling in Section S T R  
S T R  
3. Miscellaneous Property in Section S T R  
S T R

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Carl T. Kiiskila, in a field survey on July 1, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

L-3 ¼ Corner Comm. to sec.'s 1 & 12, T24N,R8E

1843 – GLO – Burt & Mullett – Set ¼ sec. post.  
W. Birch 7" N74°E 12 links  
Aspen 8" N74°W 20 links

1992 – Cert. of Survey – John Oliver, P.S.#19840 – Found  
R.R. spike.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

L-3 ¼ Corner Comm. to sec.'s 1 & 12, T24N,R8E

Found R.R. spike at surface of E-W bit road 2' south of centerline, fitting Oliver's survey and occupation to the south. Accepted found R.R. spike as the best available evidence of the position of the original corner. Found no other evidence to dispute the location for the corner. Replaced fd. R.R. spike with standard DNR monument and placed in monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-3 ¼ Corner Comm. to sec.'s 1 & 12, T24N,R8E  
Set 4" Dia. Alum. DNR cap on 1"x36" galv. Pipe

Wit: N26°E 43.00' to set N&T on SE side 22" Ash  
S63°E 79.35' to set PK&T on SW side 9" Ash  
S21°W 30.74' to E.ly to cor. of Vert. Grader Blade  
(used for fence post)  
N62°W 65.25' to set N&T on NE side 4" Ash

Signed by:

Carl T Kiiskila

Surveyor's Michigan License No.: 33981

Date:

8-10-09

