

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Isco

(County)

Located In

Corner Code #

1. Public Land Survey

T 24N R 8E K-4
T 24N R 8E K-5

2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous
Property in Section

S T R
S T R

4. Lot No:

Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on January 16, 2007 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-4 G.L.O. J. Mullett and Wm. Burt 1843 recorded a Spruce 8" diameter for quarter corner.

K-5 J. Mullett and Wm. Burt 1843 had a 14" Tamarack for corner of sections 11, 12, 13, and 14

In November of 1957 a Department of Conservation forestry crew found an old square post for corner. In 1967 the corner was re-found.
No witnesses were given.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

K-4 Re-Established the east quarter corner of section 11 by single proportionate measurement.

K-5 Found a square cedar stake for corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-4 Set 1" X 32" Pipe with standard DNR cap

Wit: 6" Cedar N32°W 22.39'
5" Tamarack S35°E 14.60'
5" Tamarack N33°W 27.40'
4" Maple S05°W 17.10'
Carsonite Post North 1'±

K-5 Set 1" X 32" Pipe with standard DNR cap

Wit: 7" Cedar N14°W 17.75'
8" Tamarack N46°E 22.20'
10" Cedar S08°E 25.60'
5" Cedar S21°E 23.68'
*8" Balsam N01°E 13.25'
*6" Cedar S21°E 9.7'

* old witnesses

Signed by:

Carl T Kiiskila

Date:

4-4-07

Surveyor's Michigan License No.:

33981

