

SURVEY &
REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -5 PM 12:49

L. C. Records: L. S. P. 204
Robert A. Goodreau
REGISTER OF RECORDS

For corners in

Iron
(County)

Located in:

Corner Code #

- | | | |
|---------------------------------------|-------------|-----|
| 1. Public Land Survey | T 42N R 31W | G-3 |
| | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling
in Section | S T R | |
| | S T R | |
| 3. Miscellaneous
Property in Sec. | S T R | |
| | S T R | |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Robert A. Goodreau in a field survey on May 16, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

G-3 Original corner established by John Burt, U.S. Deputy Surveyor, on 7 August 1849.

Original witnesses: Spruce 10 N24W 42 links
Spruce 8 S50E 28 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-3 Found 3" x 3" Wisconsin and Michigan Power Company brass monument set in concrete, as described by Frank J. Bray RLS on 14 December 1967 (Liber 2, Page 515).

Found witnesses recorded by Bray as: 8" Red Pine (Sec. 10)(N.B.T.) S77E 186.5 links
4" Red Pine (N.B.T.) S34W 110.5 links
1" ID pipe along side of monument

Corner record research on file with county representative.

PEER GROUP APPROVED

Robert A. Goodreau 11/14/2000
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-3 Accepted corner as found.

Witnesses: 19" Red Pine S 74° E 123.6'
6" Balsam Fir S 27° E 12.76' (NBT)
16" Red Pine S 38° W 73.18'
7" Balsam Fir N 74° W 45.94' (NBT)
Sign post North 1'

Note: Measurements taken to a nail in side of witnesses.

Signed by *Robert A. Goodreau*
Surveyor's Michigan License No. 43053

Date July 1, 2000

