

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. <u>42</u> <sup>N.</sup> <del>EX</del> R. <u>31</u> <sup>EX</sup> <del>W.</del>		<u>I3</u>
2. PROPERTY CONTROLL- <u>2</u> , T. <u>42</u> <sup>N.</sup> <del>EX</del> R. <u>31</u> <sup>EX</sup> <del>W.</del> ING IN SECTION_____		<u>10a &amp; 15</u>
3. MISCELLANEOUS PROPERTY IN SECTION_____ , T. _____ <sup>N.</sup> <del>EX</del> R. _____ <sup>EX</sup> <del>W.</del>		
4. LOT NO. _____ , RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Arthur O. Enger do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on see below 19\_\_\_\_, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

**A. Description of original monument and accessories and/or subsequent restoration:**

Corner I3: Maple post (Not found. No subsequent monuments found.)  
Hemlock 18 N48E 41 ( " " " " accessories " )  
Maple 12 S62W 15 ( " " " " " " )

Corners 10a & 15: Not established in original survey nor subsequently, apparently.

**B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:**

Corner I3: Re-established 5/22/74 by double proportionate measurement between corners 1 mile W, 2 miles E, 1½ miles S, and 1 mile N. There is a 1"x5' hexagonal iron rod 379 ft. E and 93 ft. N of this position, possibly someone's bad guess as to the location of this corner.  
Corner 10a: Established 6/12/74 on S. Shore of Erickson Lake on true section line between Sec. 2 & 3, 11.437 ch. N of Sec. Cor. I3.  
Corner 15: Established 5/22/74 on line between Sec. Cor. 19.934 ch. W and 1/4 cor. 19.935 ch. E. There is a 1"x8' hexagonal solid iron rod 380 ft. E and 39 ft. N of corner, same comment as in I3, above.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

Monuments for I3 and 10a: 1" I.D. x 36" iron pipe with 3½" aluminum cap.  
Monument for 15: 1" I.D. x 34" iron pipe with 3½" aluminum cap.  
Witnesses for Corner I3: Red Pine 21 S88°W (mag.) 31.3 ft. "S10, NBT"  
Red Pine 19 S74°E (mag.) 36.4 ft. "S11, NBT"  
Witnesses for Corner 10a: W. Birch 12 N80°E (mag.) 15.9 ft. "M.C., BT"  
W. Spruce 18 S7°E (mag.) 24.9 ft. "M.C., BT"  
Distances horizontal.  
Witnesses for Corner 15: Aspen 6 S33°W (mag.) 13.9 ft. "1/16S, BT"  
Aspen 6 East (mag.) 40.5 ft. "1/16S, BT"

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY Arthur O. Enger DATE November 26, 1974

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

