

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____ _____ _____
2. Property Controlling in Section	S 35 T 42N R 32W S _____ T _____ R _____ S 27 T 42N R 32W	9 (GCDB 560140) 6
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	(GCDB 460260) _____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

I, Stephan J. Szyszkoski, in a field survey on 9 05/15/14
6 05/20/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established,
monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(9-Sec. 35) Center East 1/16 corner, Section 35. Not previously monumented.

(6-Sec. 27) Northeast 1/16 corner, Section 27. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(9-Sec. 35) Established the position for the corner midway and on a straight line between Quarter
corner 1323.89' east and the Center of Section 35 1323.89' west.

(6-Sec. 27) Established the position for the corner at the intersection of straight lines connecting
opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(9) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" B.Spruce N03°W 17.95' mrkd "1/16S BT"
5" B.Spruce S61°E 14.3' do
7" B.Spruce S22°W 25.45' do
9" W.Pine N50°W 9.6' do
Set sq'd cedar post adjacent.
E= 7901772.908 N= 135239.696

(6) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
8" Poplar N33°E 7.2' mrkd "1/16S BT"
5" Maple S40°E 5.35' do
3" Maple S27°W 7.25' do
7" Poplar S61°W 1.8' do
Set sq'd cedar post adjacent.
E= 7900189.968 N= 137278.396

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID AA8081: N= 147176.690 m. E= 7895147.466 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 06/04/2014

For the Michigan Department of Natural Resources, Forest Resources Division

