



SURVEY & REMONUMENTATION

Stock No. 26273

MAR 19 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

or corners in

Iron
(County)

Located In:

Corner Code #

Public Land Survey

T 42N R 33W

G-8.9b(009)

Property Controlling
In Section

S T R

Miscellaneous

S T R

Property in Sec.

S T R

IRON COUNTY
MICHIGAN
RECEIVED FOR RECORD

96 DEC 23 AM 9:19

L.C. Records 1, 7, P. 86

Gail H. Pisoni
REGISTERED DEEDS

Register of Deeds Stamp & File Number

Lot No. , Recorded Plat

Private Claims

South Witness Corner Meander corner between Sections 21 & 22, T42N R3W

Gary L. Pisoni, in a field survey on November 20, 1996, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

Description of original monument and accessories and/or subsequent restoration:

Original corner established by Guy H. Carleton, U.S. Deputy Surveyor in 1851.

Original corner: Wood Post

Original bearing trees:

Spruce	10"	S 16° E	18 links (11.88 feet)
White Pine	16"	S 55° W	20 links (13.20 feet)

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original corner evidence found.

Found a drill rod 5 feet from waters edge along an old wire fence line which is being used as the witness corner meader corner.

I accept drill rod as the best available evidence for restoring corner position.

Corner Record Research on file with County Representative.

PEER GROUP APPROVED
Gary L. Pisoni 12-11-96
COUNTY REPRESENTATIVE

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced drill rod and set a 3/4" dia. by 3 feet long aluminum rod monument with a 3" cast aluminum cap, stamped to read: Iron County Remonumentation, T42N, R33W, W.C., M.C., S-21, S-22, 1996, RLS-27457 from which I established the following new blazed and scribed bearing trees: (all measurements taken to nail in side of tree)

White Birch	5"	N 67° E	20.92 feet
Red Pine	12"	S 50° E	60.02 feet
White Pine	7"	S 09° W	28.33 feet
White Pine	30"	S 51° W	23.45 feet
Steel sign post		South	0.52 feet



796-64

Signed by *Gary L. Pisoni*

Date 12-10-96

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

L.7 P. 86