

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 24 T 42N R 34W S _____ T _____ R _____ S 24 T 42N R 34W	SMC W. of #12 (GCDB 624320) 12
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	(GCDB 640320)
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 05/05/14 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(SMC W. of #12) Special Meander Corner (S.M.C.) at the intersection of the South 1/16 line of  
Section 24 with the ordinary high water mark on the left bank of the Brule River. Not previously  
monumented.

(12-Sec. 24) Center-South 1/16 corner, Section 24. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(SMC) Established a WITNESS CORNER to the S.M.C. on the South 1/16 line of Section 24 and 24.5' west  
of the physical centerline of the snowmobile grade. The W.C. monument is 1037.30' west of 1/16  
corner #12 and is approximately 100' east of the Brule River. As the ordinary high water mark of  
the Brule River was not determined at this time, the distance from the W.C. to the S.M.C. is not  
known. The direction of the S1/16 line is the weighted mean bearing of the E-W 1/4 line and the  
South line of Section 24.

(12) Established the position for the corner midway and on a straight line between Quarter corner  
1322.48' south and the Center of Section 24 1322.48' north. From the position thus established, I  
found a 5/8" threaded rod set by persons unknown, projecting 10" a.g. S82W 11.5' distant, which I  
did not accept as marking the position for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(SMC) Set 1"IDx28" I.pipe with 2" alum. MDNR cap for  
a WITNESS CORNER TO THE S.M.C.  
Set measuring nail with MDNR tag in the side of:  
5" Poplar S46°E 75.5' mrkd "WC BT"  
4" Spruce S87°E 62.65' do  
4" W.Pine N20°E 55.9' do  
5" Maple in clump N54°W 24.6' do  
Set sq'd cedar post adjacent.  
E= 7883342.992 N= 138394.548

(12) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
4" Spruce N32°E 15.9' mrkd "1/16S BT"  
5" Spruce S50°E 3.2' do  
7" Spruce West 29.4' do  
6" Maple N50°W 23.85' do  
Set sq'd cedar post adjacent.  
E= 7883658.992 N= 138385.798

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)  
Coord. Ref.=NGS PID DI0209: N= 145460.522 m. E= 7873677.972 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 07/16/2014

For the Michigan Department of Natural Resources, Forest Resources Division

