

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 23 T 42N R 34W	J8
	S T R	(GCDB 540340)
	S 23 T 42N R 34W	5
3. Miscellaneous Property in Sec.	S T R	(GCDB 540360)
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 07/02/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(J8) Center of Section 23. Not previously monumented.

(5) Center-North 1/16 corner, Section 23. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(J8) Established the position for the corner at the intersection of 1/4 lines. The E-W 1/4 line is
a straight line between corners I8 and K8, the direction of the N-S 1/4 line is the weighted mean
bearing of the east and west Section lines.

(5) Established the position for the corner midway and on a straight line between Quarter corner
1319.78' north and the Center of Section 23 1319.78' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J8) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
11" Sugar N27°W 7.5' mrkd "C1/4 BT"
9" Sugar S80°E 15.7' do
5" Poplar S12°E 14.75' do
6" Basswood S79°W 7.6' do
Set sq'd cedar post adjacent.
E= 7882052.365 N= 138818.762

(5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
8" Sugar N69°E 29.8' mrkd "1/16S BT"
6" twin Sugar S56°E 6.05' do
7" Sugar S64°W 9.85' do
13" Sugar N55°W 8.25' do
Set sq'd cedar post adjacent.
E= 7882067.542 N= 139220.687

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).
Coord. Ref.=NGS PID DI0209: N= 145460.522 m. E= 7873677.972 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 07/16/2014

For the Michigan Department of Natural Resources, Forest Resources Division