

# SURVEY & REMONUMENTATION

FEB 21 2001

## SECTION

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

CO-DEC -5 PM 12:50

L.C. Records: L.8, P. 213

REGISTER OF DEEDS

For corners in

	Iron (County)	Located In:	Corner Code #
1. Public Land Survey		T 43N R 31W	D-7
		T R	
		T R	
		T R	
2. Property Controlling in Section	S	T R	
	S	T R	
3. Miscellaneous	S	T R	
Property in Sec.	S	T R	
4. Lot No. _____, Recorded Plat _____			
5. Private Claims _____			

Register of Deeds Stamp & File Number

I, Robert A. Goodreau in a field survey on March 21, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

#### A. Description of original monument and accessories and/or subsequent restoration:

D-7 Original corner established by John Burt, U.S. Deputy Surveyor, on 14 July 1849.  
Original corner: Cedar post

Original witnesses: Hemlock 24 N 12° E 25 links  
Fir 10 S 67° W 10 links

Arthur O. Enger RLS re-established corner on line between Section corners to the East and West on 26 April 1974 (Liber 1, Page 393-394).

#### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-7 Found 1" ID iron pipe w/ 4.5" brass cap set by Enger.

Found witnesses recorded by Enger as:

White Birch	6	N 38° W (mag.)	18.7'	"1/4S, NBT"
White Pine	6	N 31° E (mag.)	63.6'	"1/4S, NBT"
Red Maple	5	S 80° E (mag.)	35.3'	"1/4S, NBT"

Corner record research on file with county representative.

PEER GROUP APPROVED

Robert A. Goodreau 11-11-2000  
COUNTY REPRESENTATIVE

#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-7 Accepted corner as found.

Witnesses: Set 16d nails in above witnesses at recorded distances.  
8" Big-tooth Aspen S 72° W 27.20'  
Sign post North 0.75'

Note: Measurements taken to a nail in side of witnesses.

Signed by RA. GL  
Surveyor's Michigan License No. 43053

Date July 1, 2000

