

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron
(County)

Located In:

Corner Code #

1. Public Land Survey

T 43N R 31W

D-11

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Quarter Corner Between Sections 29 and 32, T43N, R31W

I, Gary L. Pisoni, in a field survey on November 29, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on July 18, 1849 by John Burt, U.S. Deputy Surveyor.

Original Corner; Yellow Birch Post

Original Bearing Trees:

White Pine	18"	N 83° W	25 links (16.50 feet)
Cedar	14"	S 82° E	33 links (21.78 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

Found a 3/4" diameter by 24" rebar marking corner position set by unknown person.

I accept the rebar as the best available evidence for restoring the corner position.

Corner record research on file with County Representative.

PEER GROUP APPROVED

Gary L. Pisoni
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, replaced the 3/4" diameter rebar with a 5/8" diameter by 30" long rebar pin with a 3" diameter aluminum cap stamped as follows: Iron County Remonumentation, T43N, R31W, 1/4, S-29, S-32, 2000, RLS 27457 from which I established the following new blazed and scribed bearing trees: (all measurements taken to a nail in side of tree)

Oak	6"	S 80° E	4.10 feet
Oak	5"	S 18° E	14.05 feet
Red Pine	17"	S 58° W	23.08 feet
Red Maple	4"	N 55° W	17.49 feet
Steel sign post		N 01° E	0.6 feet

00-095

Signed by Gary L. Pisoni Date 12-19-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN 20 1971

REVISOR MAY 1975

REVISOR JAN 1983

REVISOR OCT 1995

