

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron
(County)

Located In:

Corner Code #

1. Public Land Survey

T 43N R 31W

D-13 ✓

T 42N R 31W

D-1

T _____ R _____

T _____ R _____

2. Property Controlling
in Section

S _____ T _____ R _____

S _____ T _____ R _____

3. Miscellaneous

S _____ T _____ R _____

Property in Sec.

S _____ T _____ R _____

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:06

L.C. Records: L.S.P. 271

Gary L. Pisoni
REGISTERED SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Quarter corner to Section 32, T43N, R31W

Quarter corner to Section 5, T42N, R31W

I, Gary L. Pisoni, in a field survey on November 10, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on July 30, 1846 by John Burt, U.S. Deputy Surveyor.

Original Corner; Maple Post

Original Bearing Trees:

White Pine	12"	N 47° E	35 links (23.10 feet)
Yellow Birch	7"	N 76° W	52 links (34.32 feet)

PEER GROUP APPROVED
Iron Gary L. Pisoni 11-30-2000
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

Found a WI/MI Power Co. concrete monument with a brass cap marking corner position, flush with ground surface and stamped as follows: T43N, R31W, 1/4, S-32, S-5, T42N.

I accept the concrete monument as the best available evidence for restoring the corner position.

Found existing bearing trees set by unknown persons.

White Spruce	11"	S 18° W	48.79 feet
Red Maple	12"	N 30° W	4.49 feet

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

Balsam	5"	N 62° E	24.84 feet
Red Pine	24"	S 58° E	44.55 feet
Steel sign post		N 73° W	0.75 feet

00-039

Signed by *Gary L. Pisoni* Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN 22, 1971
REVISED MAY 14, 1975
REVISED JAN, 1983
REVISED OCT., 1995

