

SURVEY &
REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

or corners in

Iron Located in: Corner Code #
(County)

. Public Land Survey T 43N R 31W E-9
T R
T R
T R

. Property Controlling S T R
in Section S T R
. Miscellaneous S T R
Property in Sec. S T R

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC 22 PM 3: 27
L.C. Record: L. 8, P. 321
Gary L. Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

. Lot No. , Recorded Plat
. Private Claims

Quarter Corner Between Sections 21 and 28, T43N, R31W

Gary L. Pisoni, in a field survey on December 1, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

1. Description of original monument and accessories and/or subsequent restoration:

Original corner established on July 23, 1849 by John Burt, U.S. Deputy Surveyor.

Original Corner; Cedar Post

Original Bearing Trees:

Sugar	10"	N 01° W	18 links (11.88 feet)
Elm	10"	S 69° W	17 links (11.22 feet)

PEER GROUP APPROVED

Gary L. Pisoni
COUNTY REPRESENTATIVE

2. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

Found a fence line running approximately East and West and 14' North of corner position.

Restored the corner position by single proportionate measurement and on line between the Northwest and Northeast Section corners of Section 28.

Corner record research on file with County Representative.

3. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, set a 5/8" diameter by 30" long rebar pin with a 3" diameter aluminum cap stamped as follows: Iron County Remonumentation, T43N, R31W, 1/4, S-21, S-28, 2000, RLS 27457 from which I established the following new blazed and scribed bearing trees: (all measurements taken to a nail in side of tree)

Sugar Maple	13"	N 48° E	22.19 feet
Sugar Maple	11"	S 15° E	47.99 feet
Sugar Maple	6"	N 28° W	33.90 feet
Ash	7"	N 06° W	30.07 feet
Steel sign post		S 10° W	0.50 feet

30-089

Signed by Gary L. Pisoni Date 12-19-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

