

SURVEY & REMONUMENTATION

FEB 21 2001

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

00 DEC -5 PM12:49

L.C. Records: 1. 8, P. 202

*Robert A. Goodreau*  
REGISTERED PROFESSIONAL SURVEYOR

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T 42N R 31W T 43N R 31W T _____ R _____ T _____ R _____	G-1 G-13 ✓ _____ _____
2. Property Controlling in Section	S _____ T _____ R _____ S _____ T _____ R _____	_____ _____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____ _____

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Robert A. Goodreau in a field survey on May 9, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

G-1/G-13 Original corner established by John Burt, U.S. Deputy Surveyor, on 30 July 1846.

Original witnesses: Cedar 7 N12E 18 links  
Y. Pine 22 N22W 18 links

1" iron pipe w/ 4" aluminum cap placed by Frank J. Bray RLS, from 4 original bearing trees, on 1 December 1967 (Liber 2, Page 512).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-1/G-13 Found corner as described by Bray

Found witness recorded as: 22" red pine (S34)(N.B.T.) N 87° E, 148 links

Corner record research on file with county representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-1/G-13 Accepted monument as found.

Witnesses: 23" red pine N 90° E, 98.75'  
5.5" spruce N 46° E, 29.22' (NBT)  
5.5" spruce S 90° W, 11.20' (NBT)  
5.5" spruce S 10° W, 50.87' (NBT)  
sign post 1' North

Note: Measurements taken to a nail in side of witnesses.

Signed by *Robert A. Goodreau*  
Surveyor's Michigan License No. 43053

Date July 1, 2000

PEER GROUP APPROVED  
*Don Ray & Lisa* 11-14-2000  
COUNTY REPRESENTATIVE

