

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 12 T 43N R 32W	1
	S 12 T 43N R 32W	L4
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11				
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 1 03/19/13
L4 05/14/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1-Sec. 12) West 1/16 corner between Sections 1 and 12. 1943 - Holland, Ackerman & Holland plan G-154-GG for Wisconsin Michigan Power Company shows corner monumented with "pipe marker". 10" Poplar S27°E 11.3', 8" Poplar S38°W 3.5', 8" Poplar N30°E 35.5'.

(L4) Center of Section 12. 1943 - Holland, Ackerman & Holland plan G-154-GG for Wisconsin Michigan Power Company shows corner monumented with "pipe marker". 16" N.Pine N81°W 46.0', 5" W.Birch N08°W 38.5', 6" Balsam S85°E 35.8'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1-Sec. 12) Established the position for the corner midway and on the Section line between Section corner 1321.40' west and Quarter corner 1321.40' east. From the position thus established I found a Wisconsin Michigan Power Company monument, disturbed and out of position, N34°E 1.3' distant, which I did not accept as marking the position for the corner. Removed the WMPCO monument.

(L4) Center of Section 12. Established the position for the corner at the intersection of straight lines connecting opposite 1/4 corners. From the position thus established I found a Wisconsin Michigan Power Company monument N09°E 89.3' distant, which I did not accept as marking the position for the corner. Removed the WMPCO monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(1) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Poplar N73°E 7.5' mrkd "1/16S BT"
7" Poplar S56°E 16.85' do
4" W.Spruce S49°W 15.55' do
6" W.Spruce N89°W 11.6' do
Set sq'd cedar post adjacent.
E= 7902804.485 N= 152145.266

(L4) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" W.Birch N74°E 26.2' mrkd "C1/4 BT"
10" Poplar S68°E 2.1' do
5" W.Birch S04°W 1.85' do
5" W.Birch N33°W 6.0' do
Set sq'd cedar post adjacent.
E= 7903190.678 N= 151329.179

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID RL0240: N= 145070.957 m. E= 7907633.635 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 07/22/2013

For the Michigan Department of Natural Resources, Forest Resources Division

