

MAR 9 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

	<u>Iron</u> (County)	Located In:	Corner Code #
1. Public Land Survey		T <u>43N</u> R <u>34W</u>	<u>H-5</u>
		T <u> </u> R <u> </u>	<u> </u>
		T <u> </u> R <u> </u>	<u> </u>
		T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>
	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Sec.	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>
	S <u> </u>	T <u> </u> R <u> </u>	<u> </u>

IRON COUNTY
MICHIGAN
RECEIVED FOR RECORD99 DEC 30 AM 10:33
L.C. Records: L. 8, P. 131*Gary L. Pisoni*
REGISTERED SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
 5. Private Claims

Quarter corner to Sections 10 and 15, T43N, R34W

I, Gary L. Pisoni, in a field survey on June 3, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on September 2, 1851 by Guy H. Carleton, U.S. Deputy Surveyor.

Original Corner; Quarter Post

Original Bearing Trees:

Sugar	16"	S 50° E	9 lks (5.94 feet)
Yellow Birch	10"	N 40° W	33 lks (21.78 feet)

PEER GROUP APPROVED

Iron County Rep. 12-31-99

COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

Quarter corner restored by single proportionate measurement methods and on line between the Northeast and Northwest Section corners of Section 15.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, set a 2" diameter by 30" long split base aluminum pipe monument, with a 3" dia. aluminum cap stamped as follows: Iron County Remonumentation, T43N, R34W, 1/4, S-10, S-15, 1999, RLS 27457

from which I established the following new blazed and scribed bearing trees: (All measurements taken to a nail in side of tree)

Sugar Maple	13"	S 72° W	27.04 feet
Sugar Maple	12"	N 31° W	38.49 feet
Sugar Maple	8"	S 86° E	26.41 feet
Basswood	12"	S 03° W	61.45 feet
Steel sign post		N 50° W	0.70 feet

99-131

Signed by

Gary L. Pisoni

Date

*12-28-99*Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
 REVISED MAY 14, 1975
 REVISED JAN., 1983
 REVISED OCT., 1995

