

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Iron County

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. <u>44</u> N. <u>32</u> E. <u>W.</u>		<u>D13</u>
2. PROPERTY CONTROLLING IN SECTION <u>32</u> , T. <u>44</u> N. <u>32</u> E. <u>W.</u>		<u>15,16,7</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____, T. _____ N. _____ E. _____ S. _____ R. _____ W. _____		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Keith L. Sackett, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 8-9, 1984, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner D13: Original monument and accessories not found.

Corner 15: Not set on original survey nor subsequently apparently.

Corner 16: Not set on original survey nor subsequently apparently.

Corner 7: Not set on original survey nor subsequently apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner D13: Restored midway and on line between section corners East and West. Land calls to lake West check real good.

Corner 15: Established midway and on line between section corner West and $\frac{1}{4}$ corner East.

Corner 16: Established midway and on line between section corner East and $\frac{1}{4}$ corner West.

Corner 7: Established midway and on line between section corner North and $\frac{1}{4}$ corner South.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner D13: Set 1" I.D. by 32" iron pipe with 4" alum. cap.

9" R. Pine West 5.7ft. $\frac{1}{4}$ S, NBT

7" R. Pine S45E 10.2ft. $\frac{1}{4}$ S, NBT

5" R. Pine N48E 23.7ft. $\frac{1}{4}$ S, NBT

Corner 15: Set 1" I.D. by 32" iron pipe with 4" alum. cap.

12" Maple N04E 21.2 ft. 1/16S,BT

10" Maple S04W 28.2 ft. 1/16S,BT

Corner 16: Set 1" I.D. by 32" iron pipe with 4" alum. cap.

6" Maple N36W 16.3 ft. 1/16S,BT

4" Maple N03E 16.9 ft. 1/16S,BT

8" Cedar S88E 52.7 ft. 1/16S,BT

Corner 7: Set 1" ID by 32" iron pipe with 4" alum. cap.

4" Maple N40E 14.8 ft. 1/16S,BT

4" Maple S45E 25.3 ft. 1/16S,BT

3" Maple S20W 10.9 ft. 1/16S,BT

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____


(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Keith L. Sackett
CHIEF OF SURVEY PARTY
MICHIGAN REGISTERED LAND SURVEYOR
Keith L. Sackett
Department of Natural Resources

DATE 8-17-84



SURVEYOR'S MICHIGAN REGISTRATION NO. 19006