

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T 44N R 32W	G3
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 11/01/2011 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(G3) Corner common to Sections 3-4-9-10. Recorded in Liber 12 of LCR, Page 256, Iron County Records.
Reestablished by the undersigned in 2002 and monumented with a Witness Corner 549.14' west of the
corner position and on the Section line.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G3) Established a second Witness Corner to G3 on a straight line between the Section Corner G3 of
record and Quarter corner G2 of record, at the northerly margin of the marsh surrounding McCutcheon
Lake, 490.00' north of the position for G3.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G3) Set 1"IDx32" I.pipe with 4" alum. MDNR cap
for a Witness Corner 490.00' north of G3
and on the Section line.
Set measuring nail with MDNR tag in the side of:
7" Cedar N24E 4.7' mrkd "WC BT" leans south
5" Cedar N58W 3.9' do do
18" Cedar N60E 27.4' do
Cedar N10W 23.1' do
Set cedar post adjacent. Bearings magnetic.



Signed by Stephan J. Szyszkoski Date 01/11/2012
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Management Division