

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 2 T 44N R 32W	13
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 10/23/12 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(13-Sec. 2) Southeast 1/16 corner, Section 2. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(13-Sec. 2) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners. The position for the corner falls in the bottomlands of McCutcheon Creek. Established two Witness Corners on the 1/16 lines, 380.00' west of the corner and 547.00' north of the corner, both easily accessible from Deerfoot Lodge Rd.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Witness Corner on the South 1/16 line 380.00' west of the corner position:
Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" Sugar N55E 33.5' mrkd "WC BT"
6" Poplar S51E 17.5' do
6" W.Spruce S07W 27.95' do
6" Sugar S12W 25.25' do
Set sq'd cedar post adjacent.

Witness Corner on the East 1/16 line 547.00' north of the corner position:
Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Sugar N31E 2.35' mrkd "WC BT"
5" Sugar S55E 12.15' do
6" Sugar S47W 2.5' do
4" Sugar N67W 3.85' do
Set sq'd cedar post adjacent.

Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 12/18/2012

For the Michigan Department of Natural Resources, Forest Resources Division

