SURVEY & REMONUMENTATION

FEB 21 2001

				de la companya della companya della companya de la companya della
	SECTION		R RECORDATION CERTIFICA ment of Act 74, Mich. P.A. 19	ATE
ord	corners in	9		COMMENCING YEAR 2000
	lana.	Located In:	Corner Code #	RECEIVED FOR RECORD IRON COUNTY, MICHIGAN
	Iron (County)	_ Located in:	Comer Code #	
				00 DEC -8 PM 1:09 L.C. Recycle 12.8, P. 283
1. P	ublic Land Survey	T 44N R 33W	K-7	L.C. Keczelo ! L. 8, P. 283
		T R		
		T R T R		Giber felu
2. P	roperty Controlling 5	S T R		engineer of other
	Section S	S R		
	Miscellaneous S	S R		
F	Property in Sec.	S TR		Register of Deeds Stamp & File Number
4. L	ot No, Reco	rded Plat		A B C D E F G H I J K L M
5. F	rivate Claims			1
				2 6 5 4 3 1
Sect	tion Corner to Sections 13,	, 14, 23, 24, T44N, R33W		3
1.	Gary L. Pisoni . in	a field survey on Novem!	ber 21 , 2000 do hereby state	4 - 7 - 8 9 - 10 - 11 - 12 -
that	under requirements of P.A	A. 74, Michigan P.A. of 197	0, the corner points mentioned	5
in li	nes 1 and 2 above were	in conformance with regu	lations and rules therefore as	6 18 17 16 15 14 13
requ	ired in the current manual	of survey instructions of th	e United States Department of	7
the	Interior, Bureau of Land Ma ser points mentioned in line	inagement or by a decree or es 3, 4 and 5 above were in	a Court of Law and /or that the conformance with the rules of	8 19 20 21 22 23 24-
the	Michigan Board of Land S	Surveyors or by a Decree of	f a Court of Law; established,	9
re-e	stablished, monumented, r	ecovered, found as expresse	d below:	10 - 30 - 29 - 28 - 27 - 26 - 25 -
NOT	E. Not more than 2 corners	, all in the same town and rang	e. may be recorded	
IVO I	on this certificate.	, un ar uno ocario corrir una rung	o,, 20 1000100m	12 31 32 33 34 35 36
				13
		* · · · · · · · · · · · · · · · · · · ·		1)
Α.			/or subsequent restoration: arleton, U.S. Deputy Surveyor	
_	Sugar	12" N 31°E	31 links (20.46 feet	hing corners
В.	Description of corner evid	ience tound and/or method	applied in restoring or reestablis	mig comer.
	No evidence of original B.	T.s found.		
	Found a 3" diameter squ distances East, West, No	ared wood post marking cor orth, and South are consister	ner position. Wood post is appa nt with GLO distances.	roximately 50 years old and the bearings and
				DEER GROUP/APPROVED
	I accept the wood post a	is the best available evidence	e for restoring the corner position	Then Aary Leon 11-30-2000
	Corner record research o	n file with County Represent	tative.	PEER GROUP APPROVED TRAN Many Lean 11-30-June COUNTY REPRESENTATIVE
c.			established to perpetuate locating	
	as follows: Iron County R following new blazed and Red Maple Red Maple Balsam Red Maple	temonumentation, T44N, R3 I scribed bearing trees: (All n 13" N 40°E 11" S 07°E 9" N 75°W 3" N 50°W	ng rebar, flush with ground surfa 3W, S-13, S-14, S-23, S-24, 26 neasurements taken to a nail in 40.88 feet 50.36 feet 15.87 feet 34.38 feet	CHIGAN STATE BOARD OF PROFESSIONAL BUNGLE (1996) CHIGAN STATE BOARD OF PROFESSIONAL BUNGLE (1996) CHICAND SURVEYOR NO. CHICAND THE BOARD OF THE SERVING MAY 14, 1975 CHICAND THE SURVEYOR JAN., 1983 PROVISED OCT., 1996
	Steel sign post	West	0.65 feet	PISONI *
00	-051	0		LAND 3
	ned by day of	Date	11-29-2000	SURVEYOR No.
Su	rveyor's Michigan License	No. <u>27457</u>	FORM APPROVED BY MI	CHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1971
				BEVISED MAY 14,1975 SPEVISED JAN, 1983 LAND RAVISED OCT., 1996
		110	ER 8 PAGE 28	2

PAGE 283 8 LIBER