

# SURVEY & REMONUMENTATION

FEB 21 2001

## SECTION

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Iron</u>	Located In:	Corner Code #
(County)		
1. Public Land Survey	T. 44N R. 33W	L-7
	T. R.	
	T. R.	
	T. R.	
2. Property Controlling	S. T. R.	
in Section	S. T. R.	
3. Miscellaneous	S. T. R.	
Property in Sec.	S. T. R.	

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:11

L.C. Records: L.S. P. 292

*Graham J. Pisoni*  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Quarter Corner to Sections 13 and 24, T44N, R33W

I, Gary L. Pisoni, in a field survey on November 22, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

#### A. Description of original monument and accessories and/or subsequent restoration:

Original corner established in June, 1851 by Guy H. Carleton, U.S. Deputy Surveyor.

Original Corner; Wood Post

Original Bearing Trees:

Sugar Maple	10"	N 49° W	33 links (21.78 feet)
Yellow Birch	8"	S 03° E	48 links (31.68 feet)

#### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

PEER GROUP APPROVED  
*Iron County Peer Group* 11-30-2000  
COUNTY REPRESENTATIVE

No evidence of original B.T.s found.

Restored the corner position by single proportionate measurement and on line between the Northeast and Northwest Section corners of Section 24.

Found a 3" diameter wood post which bears S 16° 09 E and 66.5 feet from the single proportioned quarter corner.

Corner record research on file with County Representative.

#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, set a 5/8" diameter by 30" long rebar, flush with ground surface, with a 3" diameter aluminum cap stamped as follows: Iron County Remonumentation, T44N, R33W, 1/4, S-13, S-24, 2000, RLS 27457 from which I established the following new blazed and scribed bearing trees: (All measurements taken to a nail in side of tree)

Sugar Maple	8"	N 24° W	4.24 feet
Sugar Maple	11"	N 85° E	21.16 feet
Sugar Maple	9"	S 23° E	19.91 feet
Sugar Maple	7"	S 45° W	51.16 feet
Steel sign post		S 10° W	0.6 feet

00-060

Signed by

*Gary L. Pisoni*

Date

11-29-2000

Surveyor's Michigan License No.

27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1995

