

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: February 21, 2018

For corner(s) in: Iron County

Original Public Land Survey Corner

Corner Code

S T R
S T R
S T R
S T R

Property Corner

Corner Code

a. S 23 T 44N R 34W SMC J08-K08
b. S 23 T 44N R 34W 6 (GCDB 560360)
S T R
S T R

	A	B	C	D	E	F	G	H	I	J	K	L	M	
1														1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A. Corner History

a. Special Meander Corner on the west (right) bank of the Paint River. The SE corner of Gov't Lot 2, being also the NE corner of Gov't Lot 4, Section 23. Not established in the original survey.

b. Northeast 1/16 corner, Section 23. Not established in the original survey. Found no subsequent record.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a. Established the position for the corner on a straight line between Quarter corner K08 and Center of Section 23 J08, at it's intersection with the ordinary high water mark on the west (right) bank of the Paint River. The position for the corner was not monumented. Established a WITNESS CORNER to the SMC approx. 6 feet west of the OHWM and on the 1/4 line.

b. Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners, those to the north and east being monumented. From the position thus established I found a 2" brass Northern Paper Mills cap, no markings, affixed to a 1" ID iron pipe N57°W 8.1 ft. distant, which I did not accept as marking the position for the corner, and which I subsequently caused to be destroyed.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

a. Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
25" Cedar S48°W 27.9' mrkd "WC BT"
6" Sugar S75°W 25.9' do
4" Balsam N38°W 26.2' do
9" Spruce N10°W 47.25' do
Set sq'd cedar post adjacent.
E= 7882817.41 N= 158097.17

b. Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
19" Cedar N08°E 21.75' mrkd "1/16S BT"
5" Sugar S72°E 14.9' do
29" Cedar S13°E 18.85' do
15" Maple N84°W 16.35' do
Set sq'd cedar post adjacent.
E= 7882849.47 N= 158498.42

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum

Stephan J. Szyszkoski

02/26/2018

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908

