

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:03

L.C. Records: L.8, P.252

G. L. Pisoni
REGISTERED PROFESSIONAL SURVEYOR

Register of Deeds Stamp & File Number

_____ Iron _____ Located In: _____ Corner Code # _____
(County)

1. Public Land Survey T 45N R 34W B-13
T 44N R 34W B-1 ✓
T _____ R _____
T _____ R _____

2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____

3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Quarter Corner to Section 31, T45N, R34W
Quarter Corner to Section 6, T44N, R34W

I, Gary L. Pisoni, in a field survey on April 4, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on September 15, 1846 by Austin Burt, U.S. Deputy Surveyor.

Original Corner; Fir Post

Original Bearing Trees:

Yellow Birch	12"	N 31° E	18 links (11.88 feet)
Sugar	7"	N 48° W	24 links (15.84 feet)

On 8/17/72, Arthur O. Enger RLS DNR restored the quarter corner position by proportionate measurement and set a 1" diameter by 36" long iron pipe with a 4" diameter aluminum cap stamped as follows: T45N, R34W, 1/4, S-31, S-6, T44N, RLS 13581, recorded in Liber 1, Page 271-272 of LC records.

1972 Bearing Trees:

White Spruce	11"	S 01° E	15.2 feet
Balsam	9"	N 68° E	37.7 feet

PEER GROUP APPROVED

Iron day 8, from 11-30-2000
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

On 4/4/2000, found the above described monument and the following bearing tree:
Spruce 16" S 04° W 15.65 feet

Monument is 12" above ground surface.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

Red Maple	5"	West	35.00 feet
Red Maple	6"	N 02° W	56.83 feet
Red Maple	8"	N 75° E	50.93 feet
Steel sign post		North	0.85 feet

00-020

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN 28 1975
REVISED, MICHIGAN 1975
REVISED, MICHIGAN 1983
REVISED, MICHIGAN 1995

