

# SURVEY & REMONUMENTATION

FEB 21 2001

## SECTION

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Iron</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T 45N R 34W	A-13
	T 45N R 35W	M-13
	T 44N R 34W	A-1
	T 44N R 35W	M-1 ✓
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -8 PM 1:01  
L.C. Records: 4.8, P. 244  
*Gibson & Pisoni*  
REGISTERED LAND SURVEYORS

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Section Corner to Section 36, T45N, R35W Section Corner to Section 31, T45N, R34W  
Section Corner to Section 1, T44N, R35W Section Corner to Section 6, T44N, R34W

I, Gary L. Pisoni, in a field survey on April 3, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

#### A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on September 15, 1846 by Austin Burt, U.S. Deputy Surveyor.

Original Corner; Cedar Post

Original Bearing Trees:

White Pine	34"	S 62°E	42 links (27.72 feet)
Yellow Birch	20"	N 15°W	24 links (15.84 feet)

On 5/11/71, Arthur O. Enger RLS DNR restored the corner position from the remains of the white pine bearing tree stump and set a 1" diameter by 36" long iron pipe with a 4" diameter aluminum cap stamped as follows: T45N, R35W, R34W, S-36, S-31, S-1, S-6, T44N, recorded in Liber 1, Page 271-272 of LC records.

1971 Bearing Trees:

Red Maple	7"	S 44° E	25.4 feet
Red Maple	6"	N 67° E	16.3 feet
Sugar Maple	6"	N 70° W	9.2 feet

#### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found evidence of white pine bearing tree stump.

The above bearing trees were cut down by the U.S.F.S. for GPS purposes.

On 4/3/2000, found the above described monument and the following bearing trees established by the USFS:

Sugar Maple	6"	N 26°E	24.12 feet
Yellow Birch	5"	N 76°E	47.29 feet
Red Maple	8"	S 19°W	16.11 feet
Sugar Maple	11"	N 58°W	35.37 feet
Steel sign post		N 60°W	2.3 feet

Monument is 10" above ground surface.

Corner record research on file with County Representative.

#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Established the following new reference object:

Steel sign post	N 50° E	0.8 feet
-----------------	---------	----------

00-012

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

PEER GROUP APPROVED  
Gary L. Pisoni 11-30-2000  
COUNTY REPRESENTATIVE

