

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T 45N R 31W	I4
	T R	(GCDB 500540)
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 07/09/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(I4) Quarter corner common to Sections 10 and 11. 1980 - Reestablished by K.L.Sackett RLS midway and on line between Section corners north and south. Set 1"IDx32" I.pipe with 4" alum. cap. 9" Spruce N79°W 18.4', 9" Cherry S22°E 27.3'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I4) Found the 1980 monument bent at the surface of a sand/gravel road. Excavated to find the lower portion of the pipe straight and plumb and remonumented the 1980 position at that point. The Spruce NBT is present, in good condition, at record bearing, but the distance to it was found to be 28.4', not 18.4' as in the record. The Cherry NBT was found at record bearing and distance but is now a dead stub.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I4) Set 1"IDx28" I.pipe with 2" alum. MDNR cap 6" below the road surface  
Set measuring nail with MDNR tag in the side of:  
Spruce N73°W 28.75' old blazes (1980 NBT)  
11" Poplar S83°E 16.35' mrkd "1/4S NBT"  
6" Spruce S29°E 14.7' do  
6" W.Birch S07°W 17.95' do  
A sq'd cedar post with location poster was found  
S01°W 15.1' distant.  
E= 7910763.281 N= 170482.478



Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.  
Coord. Ref.=NGS PID AA8081: N= 147176.690 m. E= 7895147.466 m.

Signed by Stephan J. Szyszkoski Date 08/04/2015  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division