

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: 04/25/2016

For corner(s) in: Iron County

Original Public Land Survey Corner

Corner Code

a. S T 45N R 31W I06 (GCDB 500440)
b. S T 45N R 31W J05 (GCDB 540500)
S T R
S T R

Property Corner

1/16 Corner Code

S T R
S T R
S T R
S T R

	A	B	C	D	E	F	G	H	I	J	K	L	M	
1														1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A. Corner History

a.) Quarter corner common to Sections 14 and 15. 1980 - Reestablished by K.L.Sackett RLS, midway and on line between Section corners. Set 1"IDx36" I.pipe with 4" aluminum cap. Spruce S37°E 38.4'; W.Birch N68°E 45.2'.

b.) Quarter corner common to Sections 11 and 14. 1980 - Reestablished by K.L.Sackett RLS midway and on line between Section corners east and west. Set 1"IDx36" iron pipe with 3-1/2" diameter aluminum cap. W.Pine S49°E 57.5', 6" Spruce N06°E 3.2'.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) Found the 1980 monument in good condition and substantially midway and on line between Section corners 2641.73' south and 2641.79' north. Accepted same as a careful and faithful reestablishment of the position of the original corner.

b.) Found the 1980 monument in good condition and substantially midway and on line between Section corners 2629.91' west and 2630.48' east. Accepted the same as a careful and faithful reestablishment of the position of the original corner. The 1980 witness trees were not recovered.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

(a.) Found 1"ID I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" Tamarack N47°E 9.2' mrkd "1/4S NBT"
5" Spruce S86°E 14.85' do
6" Spruce S20°E 11.5' do
6" Poplar N70°W 22.65' do
Existing sq'd post adjacent.
E= 7910726.270 N= 168871.553

(b.) Fd. 1"ID I.pipe w/ 3-1/2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Poplar N36°E 31.6' mrkd "1/4S NBT"
5" B.Spruce S13°E 2.7' do
9" Poplar N75°W 23.8' do
5" B.Spruce N22°W 28.75' do
Set sq'd cedar post adjacent.
E= 7911543.288 N= 169664.660

Bearings are magnetic. Coordinates are MCS83, NAD83(2011) Epoch 2010.00, in meters
Coordinate Reference: NGS PID RL0202, E= 7917031.357 m. N= 156159.387 m.

Stephan J. Szyszkoski

08/23/2016

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908

