

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: 05/18/2016

For corner(s) in: Iron County

Original Public Land Survey Corner

Corner Code

S T R
S T R
S T R
S T R

Property Corner

1/16 Corner Code

a. S 4 T 45N R 32W 10 (GCDB 300620)
a. S 5 T 45N R 32W 14 (GCDB 300620)
b. S 4 T 45N R 32W SMC E2-F2 (GCDB 304640)
S T R

	A	B	C	D	E	F	G	H	I	J	K	L	M	
1														1
2		6		5	●	4		3		2		1		2
3					●									3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A. Corner History

- a.) South 1/16 corner between Sections 4 and 5. 1972 - Established by A.O.Enger RLS on the Section line between Sections 4 and 5 and at distance from E3 proportionate to the GLO plat. Set 1"IDx36" Iron pipe with 4" alum. Cap. W.Birch 8" N09°E 25.1'; W.Birch 8" S37°E 33.7'.
- b.) Special Meander Corner at the intersection of the E-W 1/4 line of Section 4 with the east shore of Deer Lake. 1972 - Established by A.O.Enger RLS. Set 5"x36" iron reinforced concrete cylinder with 4" aluminum cap. W.Birch 8" N68°E 9.7', B.Spruce 6" S65°E 11.2'.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) Found the 1972 monument in good condition and in the original position. The 1972 witness trees are dead and gone. Accepted the monument as a careful and faithful establishment of the position of the corner.

b.) Found the 1972 monument in good condition, with cap stamped "Northwest corner Government Lot 3 Section 4", at record bearing and distance from the W.Birch BT N68°E 9.7', in good condition. This monument was not used in a survey this date. It is being recorded to update the accessories.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

(a.) Found 1"ID I.pipe with 4" alum. MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:
7" W.Birch N17°E 31.3' mrkd "1/16S BT"
11" W.Pine N63°E 14.45' do
14" Poplar S21°E 34.4' do
3" W.Pine N33°W 13.15' do
Found a 3/4" ID iron pipe, firmly set, S07°E 19.95' distant. Set sq'd cedar post adjacent to corner.
E= 7897934.157 N= 171916.328

(b.) Found 5" dia. Concrete monument with 4" alum. MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:
11" W.Birch N70°E 9.95' overgrown blz (1972 BT)
3" Balsam S15°E 9.6' mrkd "SMC BT"
4" Spruce N68°W 3.3' do
6" Sugar N16°E 13.55' do
Corner falls at the west end of a 4' tall barbed-wire topped E-W hogwire fence.
E= 7897967.361 N= 172317.749

Bearings are magnetic. Coordinates are MCS83, NAD83(2011) Epoch 2010.00, in meters.
Coordinate Reference: NGS PID AA8081, E= 7895147.466 m. N= 147176.690 m.

Stephan J. Szyszkoski

07/12/2016

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908

