

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T 45N R 33W	H11
	T R	(GCDB 440200)
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 05/07/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(H11) Quarter corner common to Sections 27 and 34. Recorded in Liber 11, Page 182 for the Iron County Remonumentation Program in 2005 by Gary L. Pisoni, PS. Found Kimberly-Clark Corp. monument. W.Spruce 14" N61°W 39.13'; Balsam 3" N64°E 16.13'; W.Spruce 7" S60°E 26.08'; Steel sign post S22°W 0.80'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(H11) Found the Kimberly-Clark monument of record, in good condition, and at record bearing and distance from two remaining 2005 witnesses: The Balsam N64°E, in good condition with overgrown blazes, and the W.Spruce S60°E, in good condition with overgrown blazes. Made two new witnesses as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(H11) Found 1"ID I.pipe with alum. Kimberly-Clark Corp. cap. Found measuring nail in:  
6" Balsam N64°E 16.13' overgrown blazes (2005 BT)  
9" Spruce S64°E 26.1' do do  
Set measuring nail with MDNR tag in the side of:  
3" Maple S30°W 22.8' mrkd "1/4S NBT"  
5" Spruce N75°W 30.4' do  
Steel sign post is S22°W 0.80'.  
E= 7890604.490 N= 165184.997



Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.  
Coord. Ref.=NGS PID AA8081: N= 147176.690 m. E= 7895147.466 m.

Signed by Stephan J. Szyszkoski Date 08/17/2015  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division