

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>45</u> N. <u>34</u> R. <u>34</u> E. <u>W.</u>	<u>B9</u>
2. PROPERTY CONTROLLING IN SECTION <u>30</u>	T. <u>45</u> N. <u>34</u> R. <u>34</u> E. <u>W.</u>	<u>2</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ R. _____ E. <u>W.</u>	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Arthur O. Enger do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on see below 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner B9: Wood post (Not found. No subsequent monuments found.)
Hemlock 10 N 6E 43 (Not found. No subsequent accessories found.)
Sugar 14 S12W 53 (Not found. No subsequent accessories found.)

Corner 2: Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner B9: Re-established 1/22/74 proportionately on line between Sec. Corners 40.558 ch. E and 39.618 ch. W.
Corner 2: Established 3/14/74 on line between Sec. Cor. 20.279 ch. E and 1/4 cor. 20.279 ch. W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner B9: 1" I.D. x 36" iron pipe with 3½" aluminum cap.
Hemlock 20 N53°W (mag.) 30.4 ft. "1/4S, NBT"
Cedar 8 N37°E (mag.) 18.6 ft. "1/4S, NBT"

Corner 2: 1" I.D. x 38" iron pipe with 3½" aluminum cap.
Cedar 8 S33°E (mag.) 25.7 ft. "1/16S, BT"
Cedar 10 N24°E (mag.) 23.7 ft. "1/16S, BT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY Carl R. Johnson DATE April 19, 1974

APPROVED AND SIGNED BY Arthur O. Enger DATE April 19, 1974

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

