

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 45 N. R. 34 E.	C10
2. PROPERTY CONTROLLING IN SECTION	7 & 29 T. 45 N. R. 34 E.	3 & 10
3. MISCELLANEOUS PROPERTY IN SECTION	, T. N. R. E.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Arthur O. Enger do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on see below 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner C-10: Wood post (Not found. No subsequent monument found.)
 Y. Birch 6 S30E 28 " " " " " "
 Fir 6 N25W 12 " " " " " "
 Corners 7-15, 29-3, & 29-10: Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner C 10: Re-established 11/20/73 on line between Sec. Cor. 40.014 ch. to N and to S.
 Corner 7-15: Established 8/19/74 proportionately on line between 1/4 cor. 20.043 ch. E and Sec. Cor. 19.174 ch. W.
 Corner 29-3: Established 8/21/74 on line between Sec. Cor. 20.007 ch. N and 1/4 cor. 20.007 ch. S.
 Corner 29-10: Established 8/20/74 on line between Sec. Cor. 20.007 ch. S and 1/4 cor. 20.007 ch. N.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Monuments for Corners: C10, 29-3, & 29-10: 1" I.D. x 36" iron pipe with 3 1/2" aluminum cap.
 Witnesses for Corner C10: White Spruce 13 S64°E (mag.) 21.0 ft. "1/4S, NBT"
 Sugar Maple 4 S57°W (mag.) 14.7 ft. "1/4S, NBT"
 Witnesses for Corner 29-3: W. Spruce 9 West (mag.) 31.4 ft. "1/16S, BT"
 W. Spruce 12 N34°E (mag.) 37.2 ft. "1/16S, BT"
 Witnesses for Corner 29-10: Twin Red Maple 10 S60°W (mag.) 22.1 ft. "1/16S, BT"
 Sugar Maple 16 N4°E (mag.) 4.5 ft. "1/16S, BT"
 Corner 7-15: 5"x5"x5" squared cedar post scribed "1/16, 7, 8"
 W. Spruce 13 N58°W (mag.) 27.2 ft. "1/16S, BT"
 W. Spruce 6 N52°E (mag.) 27.5 ft. "1/16S, BT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Arthur O. Enger DATE May 22, 1970

Arthur O. Enger
Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

