

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 21 T 45N R 34W	14
	S 21 T 45N R 34W	6
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 6 12/18/12 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(14) South 1/16 cor. between Sections 21 & 22. Not previously monumented.

(6) Northeast 1/16 cor., Section 21. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(14) Established the position for the corner midway and on the Section line between Section corner  
1314.41' South and Quarter corner 1314.41' North. The position for the corner falls in a large open  
leatherleaf/B.Spruce bog. The monument was made firm with rocks and 4' long tamarack hubs driven  
adjacent.

(6) Established the position for the corner at the intersection of straight lines connecting  
opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
1" B.Spruce N16E 10.1' mrkd " X X "  
2" Tamarack S26E 55.4' do  
2" Tamarack S56W 28.5' do  
4" B.Spruce N77W 45.6' do  
Set sq'd Cedar post adjacent.  
N=167467.371 E=7880211.142

(6) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
4" Sugar N52E 2.4' mrkd "1/16S BT"  
8" Sugar S33E 16.55' do  
7" Sugar S67W 7.75' do  
5" Sugar N85W 13.0' do  
Set sq'd Cedar post adjacent.  
N=168269.252 E=7879828.735

Bearings are magnetic. Coordinates are MCS83, in meters

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 01/14/2013

For the Michigan Department of Natural Resources, Forest Resources Division

