

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

For corners in

	Iron (County)	Located In:	Corner Code #
1. Public Land Survey		T 45N R 34W	C-10
		T R	
		T R	
		T R	
2. Property Controlling in Section	S T R		
	S T R		
3. Miscellaneous Property in Sec.	S T R		
	S T R		

00 DEC -8 PM 1:00
L.C. Records: L. 8, P. 241
Gary L. Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Quarter Corner between Sections 29 and 30, T45N, R34W

I, Gary L. Pisoni, in a field survey on March 29, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established in July of 1851 by Guy H. Carleton, U.S Deputy Surveyor.

Original Corner: Wood Post

Original Bearing Trees:

Fir	6"	N 25° W	12 links (7.92 feet)
Yellow Birch	6"	S 30° E	28 links (18.48 feet)

On 11/20/73, Arthur O. Enger RLS DNR restored the quarter corner position by proportionate measurement and set a 1" diameter by 36" long iron pipe with a 3 1/2" diameter aluminum cap stamped as follows: T45N, R34W, 1/4, S-30, S-29, 11/20/73, RLS 13581 and recorded in Liber 1, Page 373-374 of LC records.

1973 Bearing Trees:

White Spruce	13"	S 64° E	21.0 feet
Sugar Maple	4"	S 57° W	14.7 feet

PEER GROUP APPROVED
Gary L. Pisoni
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

On 3/29/2000, found monument as described above and the following bearing trees:

Spruce	14"	S 70° E	21.65 feet
Sugar Maple	11"	S 58° W	14.78 feet

Monument is 12" above ground surface.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

Sugar Maple	10"	S 25° E	4.40 feet
Red Maple	11" (dbl)	N 27° E	42.58 feet
Steel sign post		S 48° W	0.70 feet

00-009

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 26, 1971

