

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 32 T 46N R 34W	5
	S T R	(GCDB 240160)
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 06/02/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Center-North 1/16 corner, Section 32. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Established the position for the corner midway and on a straight line between Quarter corner 1320.80' north and the Center of Section 32 1320.80' south. The position for the corner falls in the marshy margin of Pass Creek and is not accessible. Established Witness corners 178.62' west, on the North 1/16 line and 338.74' south, on the N-S 1/4 line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Witness corner 338.74' south of the corner:
Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" B.Spruce N06°W 7.7' mrkd "WC BT"
5" Tamarack S37°E 20.4' do
5" Tamarack S22°W 15.35' do
4" Tamarack S75°W 20.2' do
Set sq'd cedar post adjacent.
E= 7877952.657 N= 174592.666

Witness corner 178.62' west of the corner:
Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" B.Spruce N22°W 10.65' mrkd "WC BT"
9" B.Spruce N72°E 20.9' do
4" B.Spruce S22°W 6.3' do
5" B.Spruce S74°W 3.3' do
Set sq'd cedar post adjacent.
E= 7877900.901 N= 174696.755

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by Stephan J. Szyszkoski Date 07/08/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division