

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 15 T 46N R 34W	9
	S T R	(GCDB 460440)
	S 13 T 46N R 34W	8-L6
	S T R	(GCDB 626440)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 8-L6 01/25/16 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(9-Sec. 15) Center-East 1/16 corner, Section 15.  
Not previously monumented.

(8-L6, Sec. 13) A point on the E-W 1/4 line of Section 13, between 1/16 corner #8 and Center of  
Section L6. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(9-Sec. 15) Established the position for the corner midway and on a straight line between Center of  
Section 1346.89' west and Quarter corner 1346.89' east.

(8-L6, Sec. 13) Established the position for the corner on the E-W 1/4 line of Section 13, 384.00'  
feet east of the Center-West 1/16 corner of Section 13 (#8) and 934.64' west of the unmonumented  
position for corner L6 (intersection of 1/4 lines).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(9) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
7" B.Spruce N18°W 20.25' mrkd "1/16S BT"  
6" twin B.Spruce S72°E 13.35' do  
7" Cherry S01°W 16.9' do  
4" Balsam N52°W 14.9' do  
Set sq'd cedar post adjacent.  
E= 7881671.497 N= 179068.183

(8-L6) Set 1"IDx28" I.pipe with 2" alum. MDNR cap  
stamped P.O.L. C-C Sec. 13.  
Set measuring nail with MDNR tag in the side of:  
6" Tamarack S68°W 17.2' mrkd "POL BT"  
6" Tamarack N52°W 7.25' do  
4" Tamarack N21°E 13.5' do  
3" W.Birch S82°E 6.1' do  
Set sq'd cedar post adjacent.  
E= 7884204.724 N= 179022.781

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.  
Coord. Ref.=NGS PID RL0476: N= 196482.409 m. E= 7879234.515 m.

Signed by Stephan J. Szyszkoski Date 02/17/2016  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division