MARCH C

1

12

13

24

25

-36

AC	CEPTED BY THE ISABELLA COUNTY.				JAN .	Ĺ 9 2(101
	111.2 126/8	Isabella County Remonume	ntation Program			TION	
10	Villiam B. Raddell, Ph	LAND CORNER RECORDATI	ON CERTIFICATE N	nent 10770	Libe	ŗ Pa	дę
	ounty Representative	Filing Requirement of Act 74	I, Mich. P.A. 1970	10736		1 3	51
For co	rners in	•					
ISABI (Cour		Corner Code	200000010732 Filed for Reco ISABELLA COUNT SHARDN A BROWN On 12-08-2000 RE LAND COR Liber 1 Pag	Y, MI			
1. Puł	Dlic Land Survey T <u>15N</u> T <u>16ฝื</u> T T		Register of D				nber
in S 3. Mis	perty Controlling S	R R R					
Lot No, Recorded Plat					E F G		Γ
. Priv	ate Claims		3 3	5	4	3	2
	John H. Rauser, P.S. , in a field	survey on February 2000	4 7	- 8	· 9 ·	10	11
or fleterly certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the 6 miles unrent manual of survey instructions of the United States Department of the learning of the lines of th					16	15	14
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3,4 and 5 bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a 8 19 20 court of Law; established, re-established, monumented, re-monumented, recovered, found as 9				20	21	-22	23
vhicese				29	28	27	26
	on this certificate.	•	12 31	32	33	34	35
. D	escription of original monume	nt and accessories and/or sub	sequent restoration:				
<u>-1</u>	North 1/4 Section 6, T15N-R6W, S	<u>sherman Township, Isabella County</u> uring the original government survey			3, T16N	I-R6W	
870	A.R. Arnold - County Surveyor, Fo				,		
975	Certified Survey Act 132, L.002, Po	g. 158, Jerry Jones P.S. #19838, no	description of object giv	en. Meas	sured 25	580_9' tr	A-1

- В
- 15 1.
- Jerry L. Jones P.S.#19838,(LCRC #376)Found 3/4" solid rod, replaced with 3/4" pipe. 1976
- Certified Survey Act 132, L003, Pg. 606, Thomas Mueller P.S.#25861, Fnd 3/4" Pipe. 1981
- Certified Survey Act 132, L.005, Pg. 607 & 608 and LCRC 1369, Ronald Harris P.S.#41917, Fnd 3/4" pipe 1997
- Description of corner evidence found and/or method applied in restoring or reestablishing corner: B.
- North 1/4 Section 6, T15N-R6W, Sherman Township, Isabella County <u>B-1</u>

Corner is obliterated. Found no evidence of county survey. Area residents stated that the road was recently cut down and regraveled. Found power pole witness from 1975, gate post and White Pine from 1997. Reset corner using witnesses and monumentalion from 1975 survey. Excavated to a depth of 3.5' (well into original sand). Found no other evidence of corner. We accept the position calculated using the witnesses and found monumentation as the best available evidence of the position of the corner as originally established and monumented by the county surveyor, using GLO instructions.

Description of monument for corner and accessories established to perpetuate locating the position of the corner;

<u>B-1</u> North 1/4 Section 6, T15N-R6W, Sherman Township, Isabella County Set standard Isabella County monument and monument box in centerline of Vernon Road and Allen Road North, 6" below grade, stamped B-1, #39096

SW 69.35' Spike w/tag in 24" White Pine ST (1475) S10E 31.5 Centerline west gate post (1991) NW 601 Nail w/tag in power pole OBT (1975) South 33

3/4" pipe (1975)

Su Signed by Surveyor's Michigan License No. 39096

MICK OF JOHN H. RAUSER PROFESSIONAL SURVEYOR No. 39095

O S D SAWICHICAN

ESSION

00 OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

DAPTED FOR WORD PROCESSING MARCH, 1995