

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>16</u> T. <u>2</u> N. S. R. <u>2</u> E. W.		E-5, E-6
2. PROPERTY CONTROLLING IN SECTION _____ T. _____ N. S. R. _____ E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ N. S. R. _____ E. W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Donald L. Bissell, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October 17, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

<p>E-5 S75°30'W, 12.19', 18" Oak S20°E, 8.32', 16" Oak N07°E, 55.18', SW Cor. House West, 120.0', E road S75°E, 13.31', 11" Oak</p>	<p>E-6 19" Triple W. Cherry, S23°W, 21.79' 11" W. Cherry, S00°W, 38.35' At North side of Rail-road tie anchor post.</p>
---	--

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

<p>E-5 Found 1" pipe flanged out to 3"</p>	<p>E-6 Found ½" pipe North side of rail-road tie anchor post.</p>
--	---

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<p>E-5 S75°30'W, 12.19', 18" Oak S20°E, 8.82', 16" Oak N07°E, 55.18', SW cor. house S75°E, 13.31', 11" Oak Placed ½" pipe with plastic cap #18655 Inside 1" pipe.</p>	<p>E-6 S03°W, 68.20', 14" Hickory S12°W, 38.22', 15" B. Cherry S36°W, 42.90', 13" Oak S42°W, 21.40', 12" Triple Cherry South, 0.5', center fence post placed plastic cap #18655 in pipe.</p>
--	---

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY Donald L. Bissell DATE 11-22-77
CHIEF OF SURVEY PARTY
 MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

STATE OF MICHIGAN REGISTERED NO. 11177