,	JACKSON COUN APPROVED LAME							
	P.A. 342 of 10			SECTION 27 S TOWNSHIP			#2023681 Liber 153	4 Page 20
	Dec. 26	1996 4	ND CORNER REC	ORDATION CER	TIFICATE		Page 1	of 1
_			ing Requirement	of Act 74, Mich.	P.A. 1970		Jackson C	o., MI
Fo	r corners in JACKSON	÷			i		Recorded 12/27/96	1:2::07P
	(County)	Located	in: Co	rner Code ##			Jerry McD	
	·	1	S _ 2W	H-10			Register	
1.	Public Land Survey	T	_ R					
		T	- H - 3F	MICHICAL				
		T	R \$ 6	1				
2.	Property Controlling	S T	R T TONA	LD L. XX				
	in Section	S T						
3.	Miscellaneous	S T		Z A	Reç	gister of Deeds S	tamp & File	Number
	Property in Sec.	S T	- H <b>教</b>	09				
4.	Lot No,	. Recorded Plat	CENSED LAN	AVE A		4 B C D	E F G H	
	Private Claims		LAN	D SO, TA		A B C D	EFGH	IJKL
						2 - 6 - 5 -	- 43	<del>         </del>
						3		1 1 1 1
	RONALD L. ENGE	R in a field survey.	DECEMBER	20	96	5 5 5	9—10— 	11-1-12
do	hereby certify that under r	in a neig survey in a neighbor survey in a neighbor survey in a neighbor survey in a neighbor survey in a	Michigan P.A. of 1970,	,	ntioned	6 18 17		
	lines 1 and 2 above were		_			7   1	16	14-11
	rrent manual of survey ins inagement or by a decree (					8 10 20	21 22	23 24
	ove were in conformance		•	•		9		
	ourt of Law; established, pressed below:	, re-established, mon	umentea, re-monume	ntea, recoverea, lot	ing as	10	23 0	2625
NC	TE: Not more than 4	corners, all in the s	ame town and rang	e, may be recorded	Ь	11	++	
	on this certificat		_	•		12 31 32	3334-	35 36
					_	13		
A.	Description of origina				n:			
	1. POST NOT SET 2. ALAN SCHEPPE	IN ORIGINAL	GOVERNMENT S	SURVEY	ACT 74 (	PERTIFICATE	INTER	R A
	PAGE 276 IN MAY	ELMAN PS 3098 / 100/ AS A SET	S RECORDED C	AT INTERSECT	FION 3	LINES	IN LIBE	IN <del>"7</del>
	NAIL & TAG IN S				•			
	NAIL & TAG IN E	. SIDE DBL 12"	& 14" HICKORY	N30°W 34.5	1'			
	NAIL & TAG IN E	. SIDE 20" WAL	NUT S40°W 3	3.59'				
	NAIL & TAG IN S	S. SIDE 16" OAK	S70°E 43.66′					
_	Description of corner	r avidence found one	Var mathad applied	in restoring or rees	etablichina	corner:		
D.	Description of comer	evidence lound and	yor method applied	in restoring or rees	stabilishing	comer.		
	SEARCHED AT A	PPARENT LOCA	TION OF CORNE	R AND FOUND	- <del>1</del> " BAR	& CAP #3599	8 ON	
	CENTERLINE AB	BEY ROAD AND	7.5' SOUTH OF	FENCE LINE	TO EAST	& WEST. TR	AVERSE	OF
	SECTION 27 SHO	WS BAR & CAP	TO LIE 0.11 SO	UTH & 0.41 EA	ST OF I	NTERSECTION	I OF ∄ L	INES.
	ACCEPTED 1 BA	AR & CAP AS CE	NTER OF SECT	ION BECAUSE	OF CLO	SE PROXIMIT	Y TO	ΑŦ
	INTERSECTION (	OF # LINES AND	DIACED BAB &	CAD WITH STA	SCHEPP SUDARD	YELMAN TO P MONUMENT	LACE II	Ai
	INTERSECTION	OF A LINES. NE	PLACED BAIL &	OAL WITH OIL	NI DAILD	MONOMENT		
_	Description of monun		acconnerine actablic	had to perpetuate	locating th	e position of the	comer	
U.	H-10 T1S R2W	HERE FOI COTTET AIRO &	avvossories establis	to perpetuate	. searing til		_ = - / / = - +	
	4" DIAMETER BY	36" LONG CON	CRETE MONUMI	ENT WITH ALL	MUNIM	CAP STAMPE	D LS 284	109
	079° NAZ 21"	OAK	<b>47.70'</b>	NAIL & TAG	IN SOUT	'H SIDE		
	095° NAZ		22.30'	SURVEY MAR				
	166° NAZ 23"	OAK WALNUT	85.30' 33.65'	NAIL & TAG NAIL & SHIN				
		HICKORY	34.55'					
	349° NA7 22"	OAK	60.23	NAIL & TAG	IN EAST	SIDE		
	NOTE: NAIL & TA	AGS ARE 20D SF	IKES AND YEL	LOW PLASTIC	TAGS S	STAMPED PS	25837	
	NOTE: NAZ IS MA	AGNETIC AZIMU	TH MEASURED	FROM NORTH.				
		_						
	16.64	16		Date	DI	ECEMBER 21,	1996	_

28409

Surveyor's Michigan License No.