JACKSON												
PROVED LA	AND CORNER of 1990/ . ^											
airman <u>M</u> e	Northwest Corner of Section 5,		-									
Date De	E 11, 1996 LAND CORNER RECORDATION	ON CERTIFICAT	E									
	Filing Requirement of Act 74,	Mich. P.A. 1970				#2022	225 1533	r Dage	. 122			
For corners in JACKSON Located In: Corner Code #						Page		of i	. 144			
	Dounty)	Located III.			Jackson Co., MI							
1. Public La	ind Survey T2S R1E C-1	Recorded										
.,	TR					12/11/96 10:58A Jerry McDevitt						
	t						ster (ed≲			
2. Property	Controlling ST_R	}										
in Sectio 3. Miscellar	'' ''''''' ''''''''''''''''''''''''''''	ļ										
Property	in Sec. STR	Re	gister	of De	eds St	amp &	File N	umbe	r			
4. Lot No.	, Recorded Plat	_	, A B Ç D E F G H I J K L M									
5. Flivate C	idili15		2						T .			
			3	6	5	- 4	3	2	. 1			
			4	7	. ś	9	10		12			
t , <u>David E, Erickson</u> , in a field survey on <u>April 17</u> , 19 <u>96</u> , do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned						<u> </u>	1					
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land			6	-18	- 17 -	16	15	14	13			
Management or by a decree of a Court of Law and/or that the corner points mentioned in tines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a			7				<u> </u>		 			
Court of Lav	v; established, re-established, monumented, re-monumented, recov		8	19	20	21	22	23	24			
expressed bei	W:		10	30	29	28	27	26	25			
	more than 4 corners, all in the same town and range, may be reco	rded	11			2						
			12	31	32	33	34	35	36			
A. Descri	otion of original monument and accessories and/or subsequen	t restoration:	13	2		: .		L	L			
	Parke - Deputy Surveyor, set a "Post" and recorded 2 wit	messes: "W. Oal	c 24, s	S50°E,	156"	(102.9	6') and	"W. (Dak			
28, S34°W,	93" (61.38').											
	F. Bean reported "found remains of post & witnesses" of "B. Cherry 6, S73°W, 145 1/2" (96.03').	and recorded 2	witnes	sses:	"Мар	le 3, N	176 1/2	2°W, 1	87"			
-		an ton OMS beat	6						.los			
set iron be	itekunst Surveyors "found Fire Clay (FC) 1.8' below surfa side F.C. Jog East 93,06' Gov't. 94.0' measured" four wi	ce, top offu brok tnesses were tak	en on	th two	troft o being	note:	d as b	eing fi	rom			
	information was provided on a "Witness Card".							_				
In 1979. R.	W. Keller - LS #20707, recorded the corner as "found 1"	" iron in centerli	ne ro:	ad" pe	er Lan	d Con	ner Re	cordat	tion			
Certificate	(LCRC) at Liber 3, Page 209. Keller references the corne iber 974, Page 779 and Liber 993, Page 1195.	er in Certificate o	f Sur	veys (COS)	record	ed at I	Liber 9	967,			
B. Descri	ption of corner evidence found and/or method applied in resto	ring or reestablishi	ng col	mer:								
	x 18" iron pipe (IP) 0.5' below centerline of road. Below				40° ID	and a	third	410" •	(2)			
pinch pipe. standard t	Second and third IP's are on North and South sides of pwnship line. Left FC in place and buried three iron	' a FC which is 2 pipes over FC.	.7' be Acce _l	low s pted F	urface. Cas	. FC i a care	s 1.61 eful ar	' Norti id fait	n of hful			
perpetuatio	on of the position of the original corner defining the line be nument (JCSM) 1.61' South of the FC, on the line between	tween Sections 5	and and a	6. Set	t a stai Amend	ndard . led Co	Jackso mer p	on Cou esition	inty i on			
the standar	rd township line. Set County Surveyor sign post on North	side of road.	M1144 44	c the i	111101110	<u></u>	·······					
C. Descr	ption of monument for comer and accessories established to	perpetuate locating	g the p	ositio	of the	come	r:					
Set 4" x 36 T2S-R1E, 1	" concrete monument with 1/2" $ imes$ 36" rebar and Jackson (996".	County standard	alumi	num c	ap sta	mped	"LS #2	29245,	C-1			
NI OEO E	Cat Nail 9 Tag #20245 Cauth aids 46" Dlack Charac	37.87'		_s@_	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1							
N 25° E N 85° E	Set Nail & Tag #29245, South side 16" Black Cherry Set Nail & Tag #24295, South side 20" Hickory	37.67 155.01'			وران مسمعتصم	Li / Ch	C. The	L				
N 64° W	Set Nail & Shiner, South side 30" Oak	96.03'	Á	6			12 A					

Signed by Laure, when Date 12-9-96
Surveyor's Michigan License No. 29245 FORM APPROVED BY MICHIGAN STATE BOA

Set Nail & Tag #29245, Southwest side Power Pole

Corner C-13, T1S-R1E, JCSM

Fire Clay (Buried 2.7')

NOTE: Bearings are magnetic.

Northeast corner of House #3989 (Root Station Road)

N 37° W

S 25° W

East

North

DAVID E.
ERICKSON
Land Surveyor
No.
29245

134.43

125.97

93.92'

1.61"