## EAST 1/4 POST SECTION 25 SUMMIT TOWNSHIP

## SURVEY & REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Ear an	rners in	Filing Red	quirement of Act 7	4, Mich. P.A. 1970	•	MAK T 3 5000	
	Jackso (County)	Located In:	Carner C	ode #		SECTION	
1. Pu	blic Land Survey	T <sup>3</sup> S R 1 T R _ T R _				39384	
in: 3. Mis	operty Controllin Section scellaneous operty in Section	ST R _ ST R		1	RREM L-	ge: 1 of 2 106/1999 11:41A 1616 P-1238 (s Stamp & File Numb	oer
4. Lo	t No.	, Recorded Plat					
					- A B C	D E F G H I J	K L
	othy B. Gieson	, in a field survey on <u>Octo</u>	ober 08	. 19 98 .	3 4 7 5	8 -9 10 -11	12-
	by certify that und	er requirements of P.A. 74, Michiga e in conformance with regulations	in P.A. of 1970, the con	er points mentioned	6-18-	17 16 15 14-	13-
manual	of survey instru	ctions of the United States Dep	partment of the Interio	r, Bureau of Land	7		
5 above	e were in conform	ree of a Court of Law and/or that the ance with the rules of the Michigan	an Board of Profession	al Surveyors or by a	8 19	20 21 22 23	24-
	of a Court of Law essed below:	; established, re-established, monu	rmented, re-monument	ed, recovered, found	10 -30	29 28 27 26	25-
•		4 corners, all in the same town	and range, may be r	ecorded	11		++
	on this certifica	ite.	-		12 - 31	32 33 34 35	36-
M-10:	G.L.O. red	pinal monument and accessori ords do not indicate	how this corne	er was set.	14		
M-10:	"Fire Clay	ation survey dated 18	386			remains of witn	esses
	Willow 10"	S 57-1/4° E 7-1/4 13 S 28-1/2° W 69-1/2 13	ks. (4.785)	H.F. Bea	m 1990		
M-10:	Jackson Co	unty Road Commission d	lated 1948 (Fro	m Richard E. G	utekunst r	ecords)	
	"1" Iron E 20" Oak	N 60-30 W 50.35'	it 18" deep in	line with fenc	e North."	·	
		N 05-30 E 54.30' N 44-15 E 22.85'	(See	back for addit	ional supp	orting document	at 1on
B. De	escription of con	ner evidence found and/or me	thod applied in resto	ring or reestablishin	g comer:		
W-10:	Found Rich	ard E. Gutekunst 3/4" y 17" iron hook below	'iron pipe. E	xcavated at sa	id location	n and found 1"	
	OI 2.3'E D	elow existing ground	surface. At a	depth of 2.8'	t found br	ick memoriale	pth
	surroundin	g fire clay. Fire cl	ay is 0.46' So	uth and 0.26'	West of fo	und 3/4" Pipe.	
	Accepted f	ire clay as faithful	and careful pe	rpetuation of	Corner M-1	0.	
	Set standa East side	rd Jackson County Rem of concrete monument	onumentation " at a depth of	Concrete" monu	ment. Lef	t fire clay on	
			ar a copia or	r = below top	OI SAIU MO	ddinen (	
C Bo	acciption of man	nument for comer and accesse	nrian antahtinbad ta	novnotveto lonetina t	ha position of t	iha aawaa	
M-10:	4" x 36" c	oncrete monument with	aluminum cap	R.L.S. No.2462	posidon (): 1 I	are control.	
	N 48° E	60-d in West side 27" 60-d in South side 14	Hickory	59.43'			
		ou-d in South side 14 Sign post	wainut	21.17' 0.8'±		SOF MION	
	S 85° E	60-đ in South side 18	" Walnut	33,66†		THE OF MILEHIA	N. S.
	S 50° E S 12° E	60-d in Southwest sid	e 16" Cherry	50.801		TIMOTHY B.	· ~ ~ \
		60-d in West side 14" 60-d in East side 31"	wainut Oak	30.69 <sup>1</sup> 51.06 <sup>1</sup>		VanglesoN LAND	\$

Signed by Timothy B. VanGleson

DERED LAND November 22, 1999 Date \_\_\_

24621 Surveyor's Michigan License No.\_

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

LAND SURVEYOR No. 24621 A (continued)

Source: P.A. 74 recorded in Liber 2 Page 637 by Douglas W. Hooth Registered Land Surveyor

No.7966

June 03, 1977 Date:

"Found Iron Pipe W/Hook. Meridian Rd S & W. As MDSH Plans File #N-13-A-1

31" Oak N-63-W 51.10 18" Hickory 86.121 N-35-E 51.06 16" W. Cherry S-48-E

18.40 3/4" Iron Pipe (West 1/4 Cor. Sec. 30 Napoleon Twp.) North

Source: Richard E. Gutekunst Registered Land Surveyor No.7863 Date: March Ol, 1974

Date:

"1" iron hook-top of hook-flat 18" deep-in line fence North."
N 60-30 W 24" Oak 50.6' 24" Hickory 5" Walnut N 45 E 58.53 4.54 East 18" Oak S 15 W 112.87' Iron for West 1/4 Post Section 30, T3S, R1E, North 18.27'



SURVEY & REMONUMENTATION

MAR 1 3 2000

SECTION