

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

KALKASKA  
(County)

Located In:

Corner Code #

2000 REMONUMENTATION

1. Public Land Survey

T.25N R.5W

K-9

T      R     

T      R     

T      R     

2. Property Controlling  
in Section

S     

T      R     

S     

T      R     

3. Miscellaneous  
Property in Sec.

S     

T      R     

S     

T      R     

4. Lot No.         , Recorded Plat         

5. Private Claims         

I, EUGENE FARRIER, in a field survey on August 9, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

K-9: Sec. Cor. Common to Secs. 23, 24, 25 & 26, T25N-R5W, Garfield Township

1852 GLO Resurvey by George H. Cannon, set post for corner; Sp. Pine 14" N 40° E 41 links; Sp. Pine 8" S 40° W 22 links.

1997, DNR forest management division form, G. R. Grieve: found red cap on re-red in pavement; 15" R Pine, N 50° E 54'; 8" J. Pine, N 27° W 47'; centerline of N-S two-track trail; 1" S of centerline of pavement.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-9: Sec. Cor. Common to Secs. 23, 24, 25 & 26, T25N-R5W, Garfield Township

Found 3/4" pipe with cap in centerline E-W road and N-S trails. N 10° W, 47.07' nail in 10" J. Pine found; N 30° E, 40.88' set nail and washer in 18" R. Pine; N 52° E, 54.37' nail in 15" R. Pine found; S 46° W, 75.51' set nail and washer in 10" J. Pine. No G.L.O. witnesses were found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-9: Sec. Cor. Common to Secs. 23, 24, 25 & 26, T25N-R5W, Garfield Township

Found 3/4" pipe with cap in centerline E-W road and N-S trails. Added 5/8" iron with brass cap in mon box.

N 10° W, 47.07', 10" J. Pine, found nail

N 30° E, 40.88', 18" R. Pine, set nail & washer

N 52° E, 54.37', 15" R. Pine, found nail

S 46° W, 75.51', 10" J. Pine, set nail & washer

Kalkaska County Peer Group accepted the above monument as the best available evidence of the position of the original corner.

Ratified by Peer Group

P.A. 345 - 1990 Kalkaska County

Chairman Eugene Farrier

Date 2-14-01

Signed by Eugene Farrier  
Surveyor's Michigan License No. 24594

Date 2-15-01



Kalkaska County Jean Hall, Register

3026814  
Page: 1 of 1  
02/18/2001 10:26A  
REMON  
LB: 6 PG: 143

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1976  
REVISED JAN. 1983  
REVISED OCT. 1995