



DOCUMENT # 3133417
STATE OF MICHIGAN
KALKASKA COUNTY
RECORDED: 01/05/2017 2:39 PM
PAGES: 2
RECORDING FEES: 30.00
JOANN DEGRAAF REGISTER OF DEEDS
BK: 4 PG: 14

Land Corner Recordation Certificate
Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Joshua R. Davidson

Field Survey Date: September 29, 2016

For corner(s) in: Kalkaska County

Original Public Land Survey Corner

Corner Code

S 22, 27 T 25N R 07W
S T R
S T R
S T R

H9

Property Controlling Corner

Corner Code

S 27 T 25N R 07W
S T R
S T R
S T R

9

Property Corner

Corner Code

S T R
S T R
S T R
S T R

Protracted Public Land Survey Corner

Corner Code

S T R
S T R
S T R
S T R

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9								●						9
10		30		29		28		27●		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A: Corner History

H9 – ¼ corner common to sections 22 & 27

9 – CE 1/16 corner section 27

- 1853 – GLO Resurvey by Thomas Whelpley –
Place for ¼ Sec. post in river – set witness ¼ sec.
post on left bank South 3.36 chs. – therefrom
bearing trees –
Tamarack 14 S66E 15
W. Birch 6 S32 ¼ W 11
- 1912 – Fargo Engineering Map #3412 – No U.S.
evidence – conventional iron crockery monument set.
Basswood 10" S77½E 0.33
Double Elm 30" N66½W 0.17

– None

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

H9 – ¼ corner common to sections 22 & 27

Found Fargo 1" X 2' long hooked end pipe with a 2' long 3" diameter pointed end wood stake & a 1.5' long 4" diameter pointed end wood stake alongside of pipe. No evidence of GLO witness post was found. Accepted the position of found Fargo pipe as a careful and faithful reestablishment of the position of the original corner. Placed a stamped 2" aluminum cap on 5/8" X 12" rebar inside found pipe, and buried wood stakes alongside of pipe.

9 – CE 1/16 corner section 27

Set stamped 2" aluminum cap on 5/8" X 34" rebar per BLM standard procedure.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

H9 – ¼ corner common to sections 22 & 27

a stamped 2" aluminum cap on 5/8" x 12" rebar driven inside Fargo 1" pipe

N18°E 63.33' to set nail & tag in E. side 21" tri. Basswood
N64°E 79.93' to set nail & tag in 24" Basswood clump
N52°W 78.55' to set nail & tag in SW. side 25" Cedar
N12°W 65.64' to set nail & tag in 10" 12" 16" tri Basswood

Set blue post 1' North

9 – CE 1/16 corner section 27

a stamped 2" aluminum cap on 5/8" X 34" rebar

N84°E 20.92' to set nail & tag in S. side 8" Cedar
S58°E 1.86' to set nail & tag in twin 7" & 11" Cedar
S43°W 17.86' to set nail & tag in NW. side 12" Cedar
N73°W 25.95' to set nail & tag in S. side 12" Cedar

Set blue post with location tag 1.3' North

Joshua R. Davidson
Certifying Surveyor's Name

January 5, 2017
Date

Professional Surveyor's License No.: 46659

Prepared By: Joshua R. Davidson
Department of Natural Resources
8015 Mackinaw Trail
Cadillac, MI 49601

