



8 0 4 1 5 3 4

Tx:4028993

2/11/2015 4:45:00 PM

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

DOCUMENT #

3123272

JOANN DEGRAAF  
KALKASKA CTY ROD

KALKASKA, MI

RECORDED ON

02/12/2015 2:05 PM

REC FEE: 14.00

PAGES: 1

BK: 3PG: 395

For Corners In:

Kalkaska

(County)

Located In

Corner Code #

1. Public Land Survey	T	25N	R	7W	K12
	T		R		
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Joshua R. Davidson, in a field survey on May 14, 2014 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

**K12 – ¼ corner common to sections 35 & 36, T25N, R7W**

- 1854 – GLO Resurvey by Thomas Whelpley – set 1/4 sec post – 1) Spruce 10" N31½°W 10; 2) Cedar 8" S64¾°E 17.
- 1915 – Fargo Engineering Map #3412 – Found old stake and remains of two witness trees, conventional iron crockery monument set. – 3) Tamarack 4" N86°W 0.35½; 4) Cedar stump 18" S89°E 0.41¼.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

**K12 – ¼ corner common to sections 35 & 36, T25N, R7W**

Found 1" X 2.3' long Fargo pipe with hooked end. Found remains of Fargo stump #4 fitting position. Accepted Fargo pipe as a careful and faithful perpetuation of the position of the original corner, and replaced it with a stamped 4" aluminum DNR cap on 1" x 48" galvanized iron pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**K12 – stamped 4" aluminum DNR cap on 1" x 4' galvanized iron pipe.**

N65°E 5.84' to set nail & tag in N. side 14" Cedar  
S18°E 12.06' to set nail & tag in E. side 9" Cedar  
S88°W 7.37' to set nail & tag in S. side 14" Cedar  
N10°E 34.82' to set nail & tag in W. side 16" Cedar  
Set Blue post 1' North



Signed by:

Date:

2-11-2015

Surveyor's Michigan License No.:

46659