



8 0 3 3 1 9 3  
Tx:4023361

1/24/2014 9:45:00 AM

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Kalkaska

(County)

Located In

Corner Code #

1. Public Land Survey	T	25N	R	7W	L11
	T		R		
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Joshua R. Davidson, in a field survey on July 30, 2013 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

**L11 – ¼ corner common to sections 25 & 36, T25N, R7W**

– 1854 – GLO Resurvey by Thomas Whelpley – set 1/4 sec post.  
– 1) Nor Pine 24" N46¼°E 1.65; 2) Nor. Pine 10" S39¾°E 1.42.

– 1915 – Fargo Engineering Map #3412 – Found one US witness down & roots of other.  
– 3) Y. Pine N49°W 2.46½; 4) Y. Pine Stub S63½°W 1.35½.

– 2007 – Unrecorded Survey, File No. 15807 – Dean Farrier, PS #41098 – Fd. ¾" pipe (Fargo), 25' S. of E-W trail along W. edge of pine plantation. – 5) N15°W, 21.17' – 12" R. Pine, set nail; 6) N75°W, 11.47' – 8" R. Pine (twin), set nail; 7) S50°W, 18.22' – 8" R. Pine, set nail; 8) S15°W, 11.15' – 12" R. Pine, set nail.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

**L11 – ¼ corner common to sections 25 & 36, T25N, R7W**

Found Fargo pipe and all Farrier accessories. Dug down and also found butter dish at base of hooked end pipe. Accepted Fargo pipe as a careful and faithful perpetuation of the position of the original corner, and replaced it with a stamped 4" aluminum DNR cap on 1" x 36" galvanized iron pipe. Placed Fargo pipe and butter dish 1' below grade and alongside DNR monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**L11 – stamped 4" aluminum DNR cap on 1" x 36" galvanized iron pipe. – Set blue post 1' North.**

S18°W 11.13' to found nail in E. side 11" Red Pine (#8)  
S50°W 18.21' to found nail & tag in SE. side 8" Red Pine (#7)  
N76°W 11.51' to found nail in S side 8" Red Pine (#6)  
N15°W 21.21' to found nail & tag in W. side 12" Red Pine (#5)



Signed by:

Joshua R. Davidson

Date:

1-22-2014

Surveyor's Michigan License No.:

46659